

2006 Honda CIVIC 1.8G		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-FD1	1,799 cc		
YEAR / REG.	MILEAGE		
2006/09	84,000 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
FD1-1100075	454 × 176 × 144 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Small scratches and dents. Paint fade and peeling on plastic parts and rear spoiler. Exterior paint fade and peeling. Interior dirty. Underbody rust. AC malfunction. Seat sagging and wear.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H18/9月	メーカー ホンダ 車名 シビック	ドア枚数 4	ボディ形状 セダン	評価点 3
車種 自家用・その他 ()	排気量 1800 CC	型式 DBA-FD1	燃料 ガソリン	駆動方式 2WD
走行 84,000 km	シフト フロア 5 MT	燃料 ハイブリッド ()	走行距離 1.8G 5速マニュアルトランスミッション走行距離8	4WD
外装色 スーパープラチナ・メタリック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
内装色 ()	乗車定員 5 人	AW	サンルーフ	革シート
左・右 ディーラー・並行	12,630 円	エアバック	ナビ	TV
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/盗難防止システム/C D				
検査記入欄 小キズ有へこみ有 P アセ有ハゲ R スポイラーハゲ 外装P アセP ハゲ ルーム内汚れ 下廻りサビ AC不良 シートへたりスレ				
修復歴 有 (馬)				
A キズ U ヘコみサレ B キズヘコミ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サビ C 腐食 X 交換車 YX 交換席				
登録No. 月 日 までにも名変更できる方				
車体番号 FD1-1100075				
シリアル No.				
FW トピ石 傷A フレ 外装 小 A・U ホイル A・曲 エアロ A・フレ	長さ cm 幅 cm 高さ cm 最大積重量 Kg			
内装 ヨゴレ シス ヤブレ コゲ コゲ穴 オーディオ穴 スレ				