

2006 Honda Integra 3HB 2.0 Type S		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-DC5	DISPLACEMENT 1,998 cc		
YEAR / REG. 2006/07	MILEAGE 134,000 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Coupe		
CHASSIS NO. DC5-2306350	DIMENSIONS (L X W X H) 439 × 173 × 140 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Repainted. Aftermarket muffler (high-tuned, racing sound). Side scuffs, peeling, scratches, dirt. Large left front fender has minor processing/modification. Left and right fenders show distortion and modification. Small scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H18/7月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 R
車名 インテグラ	グレード 2.0タイプs 5速マニユアル	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 2000 cc	型式 ABA-DC5	塗装 色別	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書 等)	
走行 134,000 km	マイル フロア 5 MT	シフト		
外装色 ホワイト	カラーNo. AAG・WAG・ ()	エアコン	装飾品のみ O印 を記入	
()	内装色 黒革定員	4人	CD	サンルーフ
ベンチ 左・右	ディーラー 走行	11,620円	エレクトロニック	ナビ
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック/盗難防止システム/HID・キセノン・ディスチャージ				
検査記入欄 色替車 社外 マフラーレーシングキア高調 リア言調・横み入み ル・ムカスレ、キズ、汚し、コスサポート加工大左Fパネル ヒズミ左右都フェンダーカ加工有小キズ有へこみ有				
修理履歴 A キズ U ヘッドライト B キズ・ヘッド P 色あせ・剥き G ガラスキズ W 燃焼跡 S サビ Q 腐食 X 交換部 XX 交換部				
先鋒No. 月 日 までに名實できる方				
車体番号 DC5-2306350				
FW トビ石 漏A フレ 外装 小 ホイル エアロ	シリアル No.			
内装 3ゴレ シミ ヤブレ コガ コグ穴 オーディオ穴 スレ	重量 全重 自重 最大積載量 Kg			