

2006 Honda Integra 3HB Type R		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DC5	1,998 cc		
YEAR / REG.	MILEAGE		
2006/03	80,000 km		
DOORS	SEATS		
3	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Coupe		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DC5-2305135	439 × 173 × 139 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Minor scratches and dents on interior and exterior. Right front dashboard warped, left front dashboard bent. Many paint irregularities.			

初年度登録	メーカー H18 /	ドアク数 3	ボディ形状 クーペ	評価点					
	車名 ホンダ インテグラ	グレード タイプR	駆動区分 2WD 4WD	R					
車種 自動車・その他()	積重量 2000	型式 CC	DC5	通称形式 内装 A・B・C					
車検 - - 年 月 日	燃料 ガソリン	ディーゼル	使用履歴書(保証書・取扱説明書等)						
走行 口内にマークを記入(左:交換 ●:点検 ※:不明) [] 万 [] 千 [] 百 [] 十 [] 円	シフト ハイブリッド	フロア 6 MT							
外装色 ブルー	カラーNo. ()	エンジン AA6・AA9・WAG・()	装備品のみ O印 を記入						
()	内装色 ()	標準定員 人							
ハンドル 左・右	変速方式 オートマチック	入力部	F5	F7					
分譲	ディーラー	走行	AW	SANLUP					
		11,400 円 + 固定費	エレクトロニクス	ナビ TV モーター					
セールスポイント									
☆ 6速ミッション									
☆ 後期型									
☆ スポーツステアリング									
☆ フロント席RECAROシート									
☆ RAYSベルサスアルミホイール									
☆ ブレンボキャリパー									
☆ エグザースタフラー									
☆ リアウィング									
検査記入欄									
内外装小傷エコー 右フィンパネ歪み 左フィンパネ曲がり Pムラ多									
修復歴 ○、無									
A	文字	U	へ30オヤレ	B	文字へ30オヤレ	D	熱処理ボルト	G	ガラスキズ
W	経修跡	S	サビ	C	腐食	X	交換済	XX	交換済
登録地									
月 日 までに変更できる									
車体番号 DC5-2305135									
FW	トピ	底	フレ	外装	小	ホイール	エアロ	シリアル	No.
内装	ゴク	シ	ヤ	コ	コ	オー	エ	メ	