

2006 Honda Integra 3HB Type S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DC5	1,998 cc		
YEAR / REG.	MILEAGE		
2006/01	97,552 km		
DOORS	SEATS		
3	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Coupe		
CHASSIS NO.	DIMENSIONS (L X W X H)		
DC5-2304705	439 × 173 × 140 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior: Significant scratches and dents have been repaired, but minor ones remain. Interior: Noticeable stains are present. Frame: No abnormalities.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H18/1月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 4
車名 インテグラ	グレード タイプS			
車種 自家用	形式 右	型式 DC5	初年式 2000	燃料 ガソリン
年 -	月 -	日 -	走行 97,552 km	変速機 AC
外装色 シルバー	カラーNo. ()	リサイクル料 11,460円	車両番号 DC5-2304705	重量 Kg
()	シフト フロア 5 MT	乗車定員 4人	長さ cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
AW サルーフ ホット
エアロパーツ

セールスポイント
ETC/運転席エアバック/A B
S/助手席エアバック/メモ
リーナビ他/アルセグTV/エ
アロパーツ

査定員記入欄

※ダメージレベルに関する注意事項
ダメージレベルは、車体の損傷の程度を示す指標です。ダメージレベルは、車体の損傷の程度を示す指標です。ダメージレベルは、車体の損傷の程度を示す指標です。

クオリティグレード説明
外装: 気になるキズやヘコミは補修済みですが、小さなキズやヘコミが残っています。
内装: 気になる汚れ等があります。
修復歴: 骨格部位に異常はありません。

車両状態の検閲
外装: 全体的に良好な状態です。一部、小さなキズやヘコミがあります。
内装: 全体的に良好な状態です。一部、小さなキズやヘコミがあります。
エンジン: 正常に動作します。
変速機: 正常に動作します。
ブレーキ: 正常に動作します。
サスペンション: 正常に動作します。
ステアリング: 正常に動作します。
電装品: 正常に動作します。