


2006 Nissan March 5HB 15G		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-YK12	DISPLACEMENT 1,498 cc		
YEAR / REG. 2006/12	MILEAGE 49,471 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. YK12-507470	DIMENSIONS (L X W X H) 372 × 166 × 152 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Hood and right front fender replaced. Left front fender repaired and painted. Windshield rubber molding deteriorated. Front and rear bumpers have scratches and scuffs underneath. Small crack on the right side sill. Dents on the right front door, left rear door, and left front fender. Tailgate closing handle is missing. Left rear taillight has a crack (may not pass inspection depending on the workshop). Steering wheel has scratches. Interior has scratches and scuffs. Seat covers are stained in several places (interior confirmed to be in good condition after removing part of the seat cover).			

ORIGINAL JAPANESE AUCTION SHEET

年式 H18 12月	メーカー 日産 マーチ	ドア数 5	ボディ形状 コンパクト/ハッチバック	評価点 3.5
車種 自家用・その他 ()	排気量 1490 cc	型式 DBA-YK12	内装 A・B・C	
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	後日選用品 (保証書・取扱説明書等)	
走行 49,471 km	CVT			
外装色 ホワイトパール	カラーNo.	エアコン	新選用品のみ・O印を記入	
()	内装色	AG・AGC・WAG・()	PS	PW
左・()	ディーラー	走行	PS	PW
9,770円	9,770円	9,770円	PS	PW
セールスポイント				
検査記入欄	修復歴 有・C			
ボンネット、右前フェンダー交換。左前フェンダー板金塗装。フロントガラスのゴムモール劣化。前後バンパー傷、下廻り傷。右サイドシルに小さな割れ。右前ドア、左後ドア、左前フェンダー内面、バックドア開める際の取っ手が欠品。左後テールランプにヒビ(工場によっては車検に通らない可能性があります)。ステアリングに傷、内張に傷、擦れ。シートカバーに数箇所汚れ。(内装シートカバーの一部を取って確認してもきれいな状態でした。)				
名義中	月 日 までに名義変更の方			
車検番号	YK12-507470			
内装	シロ	サレ	コダ	コダ
372cm	166cm	152cm	最大積載量	kg