

2006 Nissan Moco S		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
MG22S	658 cc		
YEAR / REG.	MILEAGE		
2006/10	59,720 km		
DOORS	SEATS		
5	4		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Kei		
CHASSIS NO.	DIMENSIONS (L X W X H)		
MG22S-146862	340 × 148 × 162 cm		
INSPECTOR REPORT			
Exterior has minor cosmetic imperfections. Interior has some noticeable stains. No structural damage to the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグレード鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H18/10月	メーカー 日産	ドア数 5	ボディ形状 軽四	評価点 3.5
車名 モコ	グレード S			
車種 自家用	形式 MG22S	排気量 660	燃料 ガソリン	内装 B
車検 9年11月/抹消	走行 59,720マイル	駆動 FWD	エアコン AC	最大積載量 Kg
外装色 ベージュ	カラーNo. ()	リサイクル料 9,780円	販売店 MG22S-146862	
()	シフト インパネ	AT	乗車定員 4人	長さ cm
後日送り品 (保証書・取扱説明書等)	グー・鑑定・鑑定検査報告書 日本自動車鑑定協会			
装備 ④ ⑤ ⑥ AW サルーフ セット ⑦ ⑧ ⑨ ナビ TV キーレス	グー鑑定 コンディションチェックシート E2452600205			
セルスポイント	鑑定日 2026年4月2日 再鑑定日			
CD/運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/衝突安全ボディバンチシート	クオリティグレード 外装 ★★ 内装 ★★ 修復歴 修復歴 無 機能 正常			
査定員記入欄	車両状態の説明			
	小 カードサイズ未満 中 A4サイズ未満 大 A4サイズ以上 数値 金額以上			
	ライヤラは車体の状態を詳細により判定しています。(※)表示ではありませんが、(例)車 5000円〜10000円程度修理費を要します			
	※ダメージレベルに関する注意事項 例 傷は記号のみ 小は1 中は2 大は3 さす 傷ハ ⇒ A へこみ 小 ⇒ U さす 傷 ⇒ A2 さす へこみ 大 ⇒ A3			
	F W ト ④ A フレ ⑤ ⑥ A・U ⑦ A・自 A・フレ ⑧ ⑨ シミ サブル コダ コダ ⑩ オーズ イズ スレ			
	クオリティグレード説明 外装:外観を気にしない方向けの車です。 内装:気になる汚れ等があります。 修復歴:骨格部位に異常はありません。			
	車両状態の確認は、停止状態で実施できる範囲で行っています。			