


2006 Suzuki Alto Lapin 660 SS		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE TA-HE21S	DISPLACEMENT 658 cc		
YEAR / REG. 2006/01	MILEAGE 153,000 km		
DOORS 5	SEATS 4		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR Red		
BODY TYPE Hatchback			
CHASSIS NO. HE21S-951129	DIMENSIONS (L X W X H) 340 × 148 × 151 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Door mirror P crack, front inner dent, core support heavily damaged, steering wheel trim scratches, seat sagging and wear, significant underbody rust, spoiler scratches, console scratches, exterior stains.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H18/1月	メーカー スズキ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価点 R
車名 アルトラパン	グレード 660 SS 車検9年2月11日タ イミングチェーン式エンジン	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 660 cc	型式 TA-HE21S	塗装 色式	内装 A・B・C
車検 9年2月	抹消 燃料 ハイブリッド	ディーゼル ()	後日選り込み (保証書・取扱説明書 等)	
走行 153,000 km	マイル コラム 4 AT	シフト AT		
外装色 ブライトレッド2	カラーNo. ()	エンジン ①D・AAG・WAG・()	装飾品のみ O印 を記入	
内装色 ()	乗車定員 4人	①D・AAG・WAG・()	サンルーフ	革シート
ベンチ 左・()	輸入 ディーラー・	走行 8,960 km	エレクトロニック ABS	ナビ TV キーレス
セールスポイント キーレスエントリー/ABS/運転席エアバック/助手席エアバック				
検査記入欄		修復歴 ① 無		
ドアミラーP割れ F インナU コアサポートXX ハンドルスレトリムキズウキシートへたリスレ下廻りサビR スポイラーキズコンソール傷有 外装しみ		A キズ U ヘッドライト B キズ・ヘッド P 色あせ・傷 G ガラスキズ W 燃料系 S サビ C 腐食 X 交換部 XX 交換済		
		売却日 月 日 までに名義できる方		
		車体番号 HE21S-951129		
FW トボ石 漏A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ		シリアル No.		
内装 3ゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ	長さ cm		幅 cm	最大積重量 Kg