


2006 Suzuki Swift 1.3 XG		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-ZC11S	1,328 cc		
YEAR / REG.	MILEAGE		
2006/08	20,360 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZC11S-169626	370 × 169 × 151 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Minor scratches (A) and dents on the body. Driver's seat has wrinkles.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H18/8月	メーカー スズキ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4																				
車名 スイフト	グレード 1.3 X G	駆動区分 2WD 4WD																						
車種 自家用・その他 ()	排気量 1300 cc	型式 DBA-ZC11S	通称 型式	内装 A・⑨・C																				
車検 9年8月	抹消 燃料 ガソリン ハイブリッド ()	ディーゼル ()	後日送り品 (⑨書・取付⑨書等)																					
走行 20,360 km	シフト フロア 5 MT																							
外装色 シルバー	カラーNo. ()	エアコン (A)・AAG・WAG・()	新着品のみ ○印 を記入																					
()	内装色 ()	乗車定員 5人	⑨書 ⑨書 AW サンルーフ 革シート																					
左・(A) 輸入 区分	ディーラー ()	走行 10,090 km	⑨書 ⑨書 ⑨書 ⑨書 ⑨書	⑨書																				
セールスポイント 5速 1オーナー禁煙 社外ナビTV Bカメラ キーレス 新車取説保証書																								
検査記入欄 ボディ小傷小うすA 凹み Dシートシワ		修復歴 有・⑨																						
		<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ・ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>			A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ・ヘコみ	P	色あせ/ボケ	G	ガラスキズ															
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済															
		登録No. 月 日 までに名義できる方																						
		車検 番号 ZC11S-169626																						
FW トピ石	備A シシ	ワレ ヤブレ	小 A・U	ホイール A・曲	エアロ A・ワレ	シリアル No.																		
内装 ヨゴレ	シミ	ヤブレ	コガ コガ穴	オーディオ穴	スレ	長さ cm	幅 cm	高さ cm	最大積重量 kg															