

2007 BMW 3 SERIES 320i

OVERALL

3

EXTERIOR

INTERIOR

-

-

MODEL CODE

ABA-VA20

DISPLACEMENT

1,995 cc

YEAR / REG.

2007

MILEAGE

85,000 km

DOORS

4

SEATS

5

DRIVETRAIN

2WD (FR)

TRANSMISSION

AT

FUEL

Petrol

STEERING

Right

EXTERIOR COLOR

Black

BODY TYPE

Sedan

CHASSIS NO.

WBAVA76060NL31572

DIMENSIONS (L X W X H)

452 × 181 × 142 cm

SALES POINTS

Alloy Wheels

Navigation System

Power Seats (Front)

INSPECTOR REPORT

Multiple dents on roof, hood, doors, and trunk lid (due to snow region use). All four wheels, right underside, rear bumper, and side mirrors have overall scratches. Right rear door shows signs of bodywork. Seats have wrinkles and dirt, steps have scuffs, and door panels are lifting. Headlights are dull, front bumper has a drilled hole, front bumper underside and side mirrors have minor damage (A), and tires have cracks.

ORIGINAL JAPANESE AUCTION SHEET

車種	H19	メーカー	BMW	ドア数	4	ボディ形状	セダン	評価点	3
年式	3シリーズ	グレード	320i	駆動方式	4WD	4WD			
車体	自家用・その他	排気量	1990 cc	型式	ABA-VA20	登録区分	A・B		
走行	85,000 km	燃料	ディーゼル	変速機	AT	後付部品	保証書・取扱説明書等		
外装色	ブラック	カラーNo.		エンジン	Qd・AAG・WAG	新車品のみ・O印を記入			
内装色		車庫		PS	PW	AW	サンルーフ	革シート	
走行	左・前・後・右	走行	18,260円	エアバッグ	ABS	TV	キーレス		
セールスポイント									
修復歴 有・6									
検査記入欄									
本車に對する予防整備(消耗品等)の不具合、劣化等に関しては免責事項となります。 ・検査車のためルーフやボンネット、後ドア、トランクリッドに意図的に傷が見受けられます。 ・ホイール(輪胎)右1個、右バンパー、右前ミラー、左右ミラーなど全体的に傷がございます。右前ドアには転金傷がございます。 ・シートにシワや汚れ、ステップにスレ、ドア内面に浮きが見受けられる状態です。 ・X私物関係は全て外しての検査です。 ヘッドライトくすみ、フロントバumperけ直し、フロント下回り、左右ミラーA、タイヤヒビ、									
車体番号 WBAVA76060NL31572									
寸法									
全長	452 cm	全幅	181 cm	全高	142 cm	最大積載量 kg			