

2007 Honda Crossroad 5D 1.8 18L		OVERALL 3	
		EXTERIOR -	INTERIOR -
MODEL CODE DBA-RT1	DISPLACEMENT 1,799 cc		
YEAR / REG. 2007/03	MILEAGE 168,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Blue	BODY TYPE SUV		
CHASSIS NO. RT1-1000498	DIMENSIONS (L X W X H) 429 × 176 × 167 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Steering wheel wear, interior dirty, mirror scratches and fading, small scratches, dents, paint fading and peeling, rim scratches, driver's seat opening/closing malfunction (not inspected), power window central door lock malfunction, rear gate opening/closing malfunction (not inspected).			

出品票		受取店受取番号	搬出店出取番号	シリアル番号	評価点	
前年度査定 H19 年 3 月	車 名 クロスロード	ドア数 5	グレード 1.8 18L	総走行 4800 km	評価点 4800 km	評価点 3
型式 DBA-RT1		排気量 1800 cc	燃料 ガソリン	駆動方式 前輪駆動	内装 A	色 C

車種	注消済み	車型	自家用	シート	AT	冷凍	AC	純正部品	○をつける
乗用車		16	8	0	0	0	0	0	0
全長	16	8	0	0	0	0	0	0	0
全幅	16	8	0	0	0	0	0	0	0
全高	16	8	0	0	0	0	0	0	0
外装色	ニュートロンブルー・メタリック (色替無)			カラーNo.	内装色		TVM補綴(社外品含む) ○をつける		
車台No.	RT1 -			1000498		フルセグ		ナビ補綴(社外品含む) ○をつける	
登録No.				13,470		円換算		DVD	
自重	7	1	0	0	0	0	0	後日取付け品 ○をつける	
輸入車のみの場合	モーター式			輸入区分	ディーラー	車行	ハンドル	左	新車保証書

3列シート・7人乗り・

注意事項・不具合箇所

検査員記入欄：新取戻「有」の場合は検査箇所・交換箇所を記入

ハンドルずれ有

ルーム内汚れ

ミラーギズ アセ

小キズ有へこみ有 Pアセ有 ハゲ

ドリムギズ

D席閉開不良 未検査

P席集中ドアロック不良

Rゲート開閉不良未検査