


2007 Honda Crossroad 5D 18L X Package		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-RT1	1,799 cc		
YEAR / REG.	MILEAGE		
2007/09	115,000 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Gray	SUV		
CHASSIS NO.	DIMENSIONS (L X W X H)		
RT1-1002331	429 × 176 × 167 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Overall small scratches present, full repaint.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H19/9月	メーカー ホンダ	ドア枚数 5	ボディ形状 SUV/クロカン	評価点 3.5
車名 クロスロード	グレード 18L Xパッケージ	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1800 cc	型式 DBA-RT1	通称 型式	内装 A・⑨・C
車検 - - 年 月	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送り品 (保証書・取付金等)	
走行 115,000 km	シフト AT			
外装色 グレー II	カラーNo. ()	エアコン AG・QG・WAG・()	新着品のみ O印 を記入	
(色替)	内装色 ()	乗車定員 7 人	PS	AW サンルーフ 車シート
ハンド 左・右	輸入 区分	ディーラー ・ 並行	13,470 円	ナビ付 13,470 円
セールスポイント				
検査記入欄		修復歴 有・⑨		
全体小傷あり 全塗装		A キズ U ヘコみ/サレ B キズ・ヘコみ P 色あせ/ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換済		
		登録No. 月 日 までに名義できる方 名義中		
		車検 番号 RT1-1002331		
FW トビ石 傷A ワレ 外装 小 糸いれ エアロ	シリアル No.			
内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ	長さ cm	幅 cm	高さ cm	最大積重量 kg