


2007 Honda Step Wagon 2.4 24Z		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-RG3	2,354 cc		
YEAR / REG.	MILEAGE		
2007/01	46,000 km		
DOORS	SEATS		
5	8		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Red	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
RG3-1102160	463 × 170 × 177 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Exterior has minor scratches and fading.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H19/1月	メーカー ホンダ	ドア枚数 5	ボディ構造 ミニバン/ワンボックス	評価点 4
車名 ステップワゴン	グレード 2.4 24Z 修復歴無 キーレス HDDナビ	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 2400 cc	型式 DBA-RG3	通称 型式	内装 A・B・C
車検 - - 年 / 月	燃料 ガソリン	ディーゼル	後日送り品 (保証書・取扱説明書 等)	
走行 46,000 km	シフト インパネ	CVT		
外装色 レッドレッド	カラーNo. R81	エアコン	新着品のみ O印 を記入	
内装色 ()	乗車定員 8 人	PS	サンルーフ	革シート
ハンド 左・右	輸入 区分	ディーラー	走行 12,720 円	オプション エブリック
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/HDDナビ/TC/フルエアロ/H I D・キセノン・ディスチャージ/D V D 再生/C D /バックカメラ/両側スライド片側電動ドア				
検査記入欄 外装小傷色あせあり		修復歴 有・無		
		A キズ U ヘビイサレ B キズ・ヘビイ C 色あせ・サケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換品 XX 交換所		
		登録No. 月 日 までに名義できる方 名義中		
		車検番号 RG3-1102160		
FW トビ石 傷A フレ	小 傷B	外装 A・U A・曲 A・フレ	エアロ	シリアル No.
内装 ヨゴレ シミ ヤブレ	コガ	コガ穴 オーディオ穴 スレ	車輪	長さ cm 幅 cm 高さ cm 最大積重量 kg