

2007 IS 250		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GSE20	DISPLACEMENT 2,499 cc		
YEAR / REG. 2007/10	MILEAGE 84,200 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Sedan		
CHASSIS NO. GSE20-5058689	DIMENSIONS (L X W X H) 458 × 180 × 143 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control Lexus IS Premium Sound System (13 s...	
INSPECTOR REPORT			
Steering wheel wear, seat edge wear and sagging, wheel scratches, door mirror scratches, minor scratches and dents, light interior stains.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H19 10月	メーカー レクサス	ドア枚数 4	ボディ形状 セダン	評価点 4
車名 I S	グレード 250	駆動方式 2WD	4WD	
車種 乗用車・その他	排気量 2500 cc	型式 DBA-GSE20	登録形式	内装 A・B・C
車検 - 年 - 月 / 日	燃料 ガソリン	ディーゼル	検日通り品 (保証書・取扱説明書等)	
走行 84,200 km	フロア 6 AT			
外装色 ブルーイッシュパールクリスタルシャイン	カラーNo. A00	エアコン AAG・WAG	新着品のみ O印 を記入	
小回り 左・右	乗人数 5人	ドアロック A1	サンルーフ	高シート
左・右	ディーラー 14,060円	販売店 エフエフ	TV	ナビ
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/サイドエアバック/カーテンエアバック/H D Dナビ/ETC/スマートキー/盗難防止システム/オートクルーズコントロール/H I D・キセノン・ディスチャージ横滑り防止装置 (E S C) /パワーシート/ミュージックサーバー/CD/MD/バックカメラ/M T モード付き/定期点検記録簿				
検査記入欄				
ハンドルスレ シートフチスレへたり ホイールキズ ドアミラーキズ 小キズ小凹み ルーム内うす汚れ				
修理歴 有・無				
A キズ U ヘコみサレ B キズヘコみ P 色あせサレ Q ガラスズレ W 雨傷跡 S サビ C 腐食 X 交換部 XX 交換済				
登録No. 月 日 までに名義できる方				
車体番号 GSE20-5058689				
FW トボ石 傷A フレ 外装 小 ホイール エアロ シリアル No.				
内装 300 シミ ヤブレ コゲ コガタ オーディオA				
長さ cm 幅 cm 高さ cm 最大積載量 kg				