

2007 SUBARU Legacy TouringWagon 2.0GT Spec.B		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CBA-BP5	DISPLACEMENT 1,994 cc		
YEAR / REG. 2007/09	MILEAGE 104,925 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Station Wagon		
CHASSIS NO. 155136	DIMENSIONS (L X W X H) 468 × 173 × 148 cm		
SALES POINTS			
Alloy Wheels Navigation System		LEGACY Premium Sound System (6-sp...	
INSPECTOR REPORT			
Right front dashboard warped, battery issues, electric folding door mirror faulty, studless tires, steering wheel cover, dashboard cracked, seat stains, paint peeling on mirrors/rear spoiler/exterior.			

ORIGINAL JAPANESE AUCTION SHEET

車種 H19 9月	メーカー スバル	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 R
車名 レガシーツーリングワゴン	グレード 2.0GTスペック B	駆動方式 2WD	燃費区分 40.0	
車庫 自家用・その他 ()	排気量 2000 cc	型式 CBA-BP5	通称 4WD	内装 A・B・C
車検 - 年 - 月 - 日	燃料 ガソリン	ディーゼル	検日履歴 (保証書・取扱説明書 等)	
走行 104,925 km	シフト AT			
外装色 シルバー	カラーNo. C6Z	エアコン	新着品のみ O印 を記入	
()	色別車検 (内装)	乗車定員 5 人	PS	PS
小 左・右	輸入 ディーラー	走行 13,320 km	エアロ	ABS
セールスポイント ブッシュスタート		車検 155136		
F 修復歴 右Fインパネヒズミ、BTあがり、電格ドアミラー不良、 スタッドレスト、ハンドルカバー、ダッシュ板ワレ、 シートシミ、ミラー・Rスポイラー・Pハグ、外装Pハグ		修復歴 A 欠損 B へこみ C へこみ D へこみ E へこみ F へこみ G へこみ H へこみ I へこみ J へこみ K へこみ L へこみ M へこみ N へこみ O へこみ P へこみ Q へこみ R へこみ S へこみ T へこみ U へこみ V へこみ W へこみ X へこみ Y へこみ Z へこみ		
FW		車検 155136		
内装 シロ		車検 155136		