


2007 LS600hL Rear Seat Separate Seat Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
UVF46	4,968 cc		
YEAR / REG.	MILEAGE		
2007/10	103,800 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
White	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
UVF46-5003431	515 × 188 × 148 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Leather Seats (Leather)		Cruise Control	
Navigation System		Rear Seat Entertainment (Rear Entertai...	
Mark Levinson Reference Surround Sou...			
INSPECTOR REPORT			
Steering wheel and seat wear, minor scratches and small dents, interior scratches, wheel scratches.			

ORIGINAL JAPANESE AUCTION SHEET

年式 H19 10月	メーカー レクサス	ドア数 4	ボディ形状 セダン	評価点 4																				
車名 LS	グレード LS600hL後席セパレートシートパッケージ	駆動方式 2WD	4WD																					
車種 自家用・その他 ()	排気量 5000 cc	型式 UVF46	国産 A・⑨・C																					
登録 8年10月	扶養 無し	ディーゼル ハイブリッド ()	後付選り品 (保証書・取扱説明書等)																					
走行 103,800 km	フロア	AT																						
外装色 パール	カラーNo. ()	エンジン ⑨・AAG・WAG・()	装備品のみ・⑨印を記入																					
内装色 ()	乗車定員 4人	⑨	⑨	⑨																				
⑨ 左・()	⑨ ディーラー・直行	⑨ 20,550円・現行額	⑨	⑨																				
セールスポイント サンルーフ マークレVINソンプレミアムサウンド リアエンターテイメントシステム メローホワイト本革シート ブリクラッシュセーフティシステム レーダークルーズコントロール コーナーセンサー 全席エアシート パワーシート ハンドルヒーター																								
検査記入欄 ハンドル、シートスレ コキズ、小凹み ルーム内一部キズ ホイールキズ		<table><tr><td>A</td><td>キズ</td><td>U</td><td>ハコボネサレ</td><td>B</td><td>キズ・ハコボネ</td><td>P</td><td>色あせ・サケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>腐食跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換車</td><td>XX</td><td>交換車</td></tr></table> 登録年月日 月 日 まで(に名義で所有) 車体番号 UVF46-5003431			A	キズ	U	ハコボネサレ	B	キズ・ハコボネ	P	色あせ・サケ	G	ガラスキズ	W	腐食跡	S	サビ	C	腐食	X	交換車	XX	交換車
A	キズ	U	ハコボネサレ	B	キズ・ハコボネ	P	色あせ・サケ	G	ガラスキズ															
W	腐食跡	S	サビ	C	腐食	X	交換車	XX	交換車															
⑨	⑨	⑨	⑨	⑨																				
⑨	⑨	⑨	⑨	⑨																				