

2007 Mercedes-Benz E Class E250		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-211052C	DISPLACEMENT 2,496 cc		
YEAR / REG. 2007/11	MILEAGE 75,000 km		
DOORS 4	SEATS 5		
DRIVETRAIN 2WD (FR)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Sedan		
CHASSIS NO. WDB2110522B242527	DIMENSIONS (L X W X H) 485 × 182 × 148 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Power Seats (Front) Navigation System	
INSPECTOR REPORT			
Small stone chips on the front windshield, hood, and front bumper. Minor scratches on both left and right doors and door edges. Seats show wrinkles from use. Door trims have minor scratches and dirt. The TV function is not operational. Please note that issues or deterioration related to preventative maintenance (consumables, etc.) are not covered.			

ORIGINAL JAPANESE AUCTION SHEET

年式登録 H19 11月	メーカー メルセデス・ベンツ	ドア数 4	ボディ形状 セダン	評価点 4
車種 乗用車	グレード E クラス	型式 E250	駆動方式 4WD	
車体 白	2490 cc	型式 DBA-211052C	内装 A・C	
走行 75,000 km	燃料 ガソリン	変速機 AT	後付選用品 (保証書・取扱説明書等)	
外装色 イリジウムシルバーメタリック	カラーNo. ()	エンジン (Qd・AAG・WAG・)	装備品のみ・O印を記入	
内装色 ()	車庫 ()	PS	PW	AW
左・前 左・前	右・後 右・後	ABS	サンルーフ	シート
走行距離 20,030 km	販売店 メルセデス・ベンツ	エアバッグ	TV	その他
セールスポイント		修復歴 有・C		
検査記入欄		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損		
フロントガラス、ボンネット、Fバンパーに飛び石小 右側ドアとドアエッジ部に小傷 シートと使用に伴うシワ ドア内張りにも小傷や汚れ X TVの運用はできませんでした 本車同に対する予防整備(消耗品等)の不具合、劣化等に関しては免責事項となります。		名義中 月 日 までに名義変更の方		
WDB2110522B242527		車検 485 cm 182 cm 148 cm 485 kg		