


2007 MercedesBenz Benz V Class V350 Ambiente		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
639811	3,724 cc		
YEAR / REG.	MILEAGE		
2007/08	171,900 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WDF63981123281226	476 × 191 × 193 cm		
SALES POINTS			
Alloy Wheels		Roof Rails	
Leather Seats (Leather)		Power Sliding Doors (Both Sides) (Both...	
Power Seats (Front)		Cruise Control	
Side Camera		Navigation System	
INSPECTOR REPORT			
Minor scratches on exterior, dirt/stains on interior			

年式登録		グレード メルセデス・ベンツ		トア後数 5		ボディ形状 ミニバンワンボックス		呼称番号 4																					
H19 8月		Vクラス		V350 アンビ エント		車種区分 2WD 4WD																							
車種 乗用車 ・ その他 ()	排気量 3700	型式 CC	539811			運転形式	内装 A・⑨・C																						
車検 - - 年 月 日	燃料 ガソリン	ディーゼル ハイブリッド ()	後付選り品 (保証書・取扱説明書等)																										
走行 1万7千1百900km	マイル フロア 5 AT																												
外装色 ブラック	カラーNo. ()	モナコ ④D・AAD・WAD・()	新着品のみのO印を記入																										
()	内装色 ()	乗車人数 7人	⑥	⑦	⑧	⑨	サンルーフ	⑩	⑪																				
左・前・右 G・E・F	輸入国 ドイツ	走行 20,050円	⑫	⑬	⑭	⑮	⑯	⑰	⑱																				
セールスポイント			 ※必ず																										
検査記入欄			修復歴 有。⑤																										
外装キズ 内装ヨゴレ			<table border="1"> <thead> <tr> <th>A</th> <th>キズ</th> <th>U</th> <th>へこみ割れ</th> <th>B</th> <th>キズへこみ</th> <th>F</th> <th>色あせ・汚れ</th> <th>G</th> <th>ガラスキズ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>修繕跡</td> <td>S</td> <td>ヤビ</td> <td>C</td> <td>変色</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table>							A	キズ	U	へこみ割れ	B	キズへこみ	F	色あせ・汚れ	G	ガラスキズ	W	修繕跡	S	ヤビ	C	変色	X	交換済	XX	交換済
A	キズ	U	へこみ割れ	B	キズへこみ	F	色あせ・汚れ	G	ガラスキズ																				
W	修繕跡	S	ヤビ	C	変色	X	交換済	XX	交換済																				
登録地			名義人																										
車体番号			MDF63981123281226																										
PW	ドボロ	備A	フレ	内装	小	ホイール	エアロ	シリアル	No.																				
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーチャイ	ズレ	車庫	最大積載量																				