

|                                                                                                             |                                              |                   |               |
|-------------------------------------------------------------------------------------------------------------|----------------------------------------------|-------------------|---------------|
| 2007 Mitsubishi Lancer Evolution X GSR<br>Evolution X                                                       |                                              | OVERALL<br>3      |               |
|                                                                                                             |                                              | EXTERIOR<br>-     | INTERIOR<br>- |
| MODEL CODE<br>CBA-CZ4A                                                                                      | DISPLACEMENT<br>1,998 cc                     |                   |               |
| YEAR / REG.<br>2007/12                                                                                      | MILEAGE<br>125,000 km                        |                   |               |
| DOORS<br>4                                                                                                  | SEATS<br>5                                   |                   |               |
| DRIVETRAIN<br>4WD                                                                                           | TRANSMISSION<br>AT                           |                   |               |
| FUEL<br>Petrol                                                                                              | STEERING<br>Right                            |                   |               |
| EXTERIOR COLOR<br>Other                                                                                     | BODY TYPE<br>Sedan                           |                   |               |
| CHASSIS NO.<br>CZ4A-0001683                                                                                 | DIMENSIONS (L X W X H)<br>450 × 181 × 148 cm |                   |               |
| SALES POINTS                                                                                                |                                              |                   |               |
| Alloy Wheels                                                                                                |                                              | Navigation System |               |
| INSPECTOR REPORT                                                                                            |                                              |                   |               |
| Exterior has noticeable scratches and dents. Interior has noticeable stains. No abnormalities in the frame. |                                              |                   |               |

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

|                     |                 |                       |                      |          |
|---------------------|-----------------|-----------------------|----------------------|----------|
| 初年度登録<br>H19/12月    | メーカー<br>三菱      | ドア数<br>4              | ボディ形状<br>セダン         | 評価点<br>3 |
| 車名<br>ランサー          | グレード<br>GSR     | ボディタイプ<br>EVOLUTION X |                      |          |
| 車種<br>自家用           | 型式<br>CBA-CZ4A  | 年式<br>2000            | 燃料<br>ガソリン           | 内装<br>B  |
| 車検<br>- 年 - 月 / 日   | 走行<br>12,900 km | 駆動<br>4WD             | 変速機<br>AC            | 重量<br>Kg |
| 外装色<br>フロントドア ラグパール | カラーNo.<br>( )   | リサイクル料<br>12,900円     | 車両番号<br>CZ4A-0001683 |          |
| ( )                 | シフト<br>フロア      | AT                    | 乗車定員<br>5人           | 長さ<br>cm |

後付品  
(保証書・取扱説明書等)

装備  
① サルーフ  
② ナビ  
③ セット  
④ キーレス

セールスポイント  
CD/バックカメラETC/横滑り防止装置  
(ESC)/HID・キセノン・ディス  
チャージ/運転席エアバック/後部座席  
エアバック/ABS/4WD/ターボ/ブルーレ  
イ再生/DVD再生/ミュージックプレー  
ヤー/後部座席  
査定員記入欄

※ダメージレベルに関する注意事項  
傷は記号のみ  
小傷 1  
中傷 2  
大傷 3  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C

クオリティグレード説明  
外装: 気になるようなキズやヘコミ  
があります。  
内装: 気になる汚れ等があります。  
修復歴: 骨格部位に異常はありません。

グー鑑定 コンディションチェックシート  
C87325042111

鑑定日 2026年08月21日 内鑑定日

クオリティグレード 内装 外装 修復歴 修理歴 補修 正常

車両状態の説明  
小 中 大 A4サイズ未満 A4サイズ以上 A4サイズ以上  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C

車両状態の説明  
小 中 大 A4サイズ未満 A4サイズ以上 A4サイズ以上  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C  
※ 小傷 1 ⇒ A  
※ 中傷 2 ⇒ B  
※ 大傷 3 ⇒ C