

2007 Toyota Hiace Wagon DX		OVERALL 3	
		EXTERIOR -	INTERIOR -
MODEL CODE CBA-TRH214W		DISPLACEMENT 2,693 cc	
YEAR / REG. 2007/08		MILEAGE 37,830 km	
DOORS 4		SEATS 10	
DRIVETRAIN 2WD (FR)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR Silver		BODY TYPE Minivan	
CHASSIS NO. TRH214-0009405		DIMENSIONS (L X W X H) 484 × 188 × 211 cm	
INSPECTOR REPORT			
Lower left pillar and right panel distorted, engine oil seepage, some interior scratches, headliner stains, some tears on seat backs, sign removal marks, underbody rust and some corrosion, and uneven repairs for small scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H19		メーカー トヨタ		ドア枚数 4		ボディ形状 ミニバン/ワンボックス		評価点 3																					
8月		車名 ハイエースワゴン		グレード DX		駆動方式 4WD																							
車歴 自家用・その他 ()		排気量 2700 CC		型式 CBA-TRH214W		通称 型式		内装 A・③・C																					
車検 - - 年 / 月 / 日		燃料 ガソリン		ディーゼル		後日選り品 (保証書・取扱説明書等)																							
走行 37,830 km		シフト インパネ		AT																									
外装色 シルバー		カラーNo. (1E7)		エアコン		装備品のみ O印 を記入																							
()		内装色		乗車定員 10人		PS パワーステアリング ABS ABS ナビ ナビ TV TV キーレス キーレス																							
ハンド 左・右		輸入 区分		ディーラー・並行		リサイクル料 15,250円		販売税 エコバック																					
セールスポイント																													
検査記入欄					修復歴 有・③																								
左ピラー下部ヒズミ、Rパネルヒズミ、EGオイルにじみ、ルーム内一部キズ、天張シミ、シート裏一部キレ、看板はがし跡、下廻りサビ、一部腐食、小キズ・小凹補修ムラ					<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズ/へこみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>					A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズ/へこみ	P	色あせ/ボケ	G	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
登録No.					名義中																								
車体番号					TRH214-0009405																								
シリアルNo.																													
内装					<table border="1"> <tr> <td>ヨコ</td><td>シミ</td><td>ヤブレ</td><td>コガ</td><td>コガ穴</td><td>オーディ穴</td><td>③</td> </tr> </table>					ヨコ	シミ	ヤブレ	コガ	コガ穴	オーディ穴	③													
ヨコ	シミ	ヤブレ	コガ	コガ穴	オーディ穴	③																							