

2008 Daihatsu Mira 5D X		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-L285S	DISPLACEMENT 658 cc		
YEAR / REG. 2008/03	MILEAGE 88,184 km		
DOORS 5	SEATS 4		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Kei		
CHASSIS NO. L285S-0013240	DIMENSIONS (L X W X H) 340 × 148 × 153 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Minor scratches on interior/exterior, light interior stains, alloy wheel scratches (A). Multiple cracks on front left bumper bottom. Rear left bumper has A1 scratch and multiple paint touch-ups. CD player jammed. One headliner stain. Undercarriage rust spots. Numerous exterior paint touch-ups. Driver's seat wear/sagging. Dashboard residue. Rear seat burn hole. Core support distortion (1). Right center pillar B1.			

ORIGINAL JAPANESE AUCTION SHEET

H20/3月		ダイハツ		5		軽四		3.5	
ミラ		X		2WD		900			
車種 自家用・その他 ()		排気量 660 cc		型式 DBA-L285S		内装 A・⑤・C			
年 9 月 3 日		燃料 ガソリン		ディーゼル		後日送り品 ()			
走行 88,184 km		フロア 4 AT							
外装色 シルバー		カラーNo. S28		エアコン AG・⑤・WAG・()		新着品のみ O印 を記入			
()		内装色		乗車定員 4 人		サンルーフ		シート	
左・()		ディーラー		走行 8,640 km		ABS ナビ TV		⑤	
セールスポイント		ETC/運転席エアバック/キーレスエントリー/助手席エアバック4WD		Y1 Y1		A1 TP		B1 TP	
検査記入欄		内外装小傷 / 内装汚れ / AWスリA / 前左バンパー底ヒビウレ複数 / 後左バンパーA1とTP複数 / CD読み不良 / 天張りシミ1 / 下廻り錆浮き / 外装TP跡多し / 運転席シートスレヘタリ / ダッシュボード付着物 / 後座シートコグ穴 / コアサポート歪み1 / 右センターピラーB1		A キズ B へこみ・凹み C キズ・へこみ D キズ・へこみ E 色あせ・汚れ F ガラスキズ W 腐蝕 H サビ I 変色 J 変色 K 変色 L 変色 M 変色 N 変色 O 変色 P 変色 Q 変色 R 変色 S 変色 T 変色 U 変色 V 変色 W 変色 X 変色 Y 変色 Z 変色		広島 581		名変中	
月 日		L285S-0013240		581		581		581	
581		581		581		581		581	