

2008 Dodge Nitro SXT		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE KA37	DISPLACEMENT 3,700 cc		
YEAR / REG. 2008/12	MILEAGE 44,532 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE SUV		
CHASSIS NO. 1D8G958K58W216282	DIMENSIONS (L X W X H) 458 × 186 × 179 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Roof Rails Side Camera	
INSPECTOR REPORT			
Medium seat scuffs, small A-grade damage on pillar trim, fine exterior scratches, A-grade damage on mirror, medium steering wheel scuffs, minor exterior scratches.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		型式番号	15743	車両種別	0102	シリアル番号			評価点
年	月	日	車名	グレード	駆動				4
H 20	12		ナトロ	5	2WD				
型式	ABA-KA37		排気量	3,700 cc	燃料	ガソリン	軽油	ディーゼル	
車種	年	月	車種	シフト	4AT	冷房	AC	純正装備品	○をつける
走行距離	4	4	5	3	2	km	○をつける	純正ナビ	SR
外装色	元色	色替無	カラーNo.	内装		純正ナビ	革シート	SR	
車台No.	1D8G958K58W216282		リサイクル	19,940円	未償還	フルセグ	ワンセグ	アナログ	
登録No.	抹消		リサイクル	19,940円	未償還	ナビ装備	ナビ装備	ナビ装備	○をつける
定員	5人	乗客	長さ	458 cm	幅	186 cm	高さ	180 cm	
輸入車のみ	モデル	年式	輸入区分	ディーラー	並行	ハンドル	左	右	
セールスポイント									

注意事項・不適合箇所			
AIS検査 & 自社査定			
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入			
シートずれ (中)			
ビラー内張A (小)			
外装薄線キズ			
ミラーA			
ハンドルずれ (中)			
外装小傷あり			
ドアミラー	キズ	ヒビ	フレ
上指	無	シヤキキ	無