

2008 Honda Fit G Highway Edition		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
DBA-GE6	1,339 cc		
YEAR / REG.	MILEAGE		
2008/06	127,734 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
White	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GE6-1161359	390 × 170 × 153 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
No AC issues, no hail damage or fading on roof, no pet hair in interior, no underbody rust or corrosion holes, no check engine light. Steering wheel has a tear, navigation buttons are malfunctioning.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H20/6月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4
車名 フィット	グレード Gハイウェイエディション	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 1300 cc	型式 DBA-GE6	通称 型式	内装 A・B
燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)		
走行 9年12月 127,734マイル	シフト フロア	AT		
外装色 ホワイト	カラーNo. AG・6AG・WAG・()	装備品のみ O印 を記入		
()	内装色 5人	PS	PW	AW
左・右 ディーラー・並行	リサイクル料 0円・()	エアバック	ABS	ナビ
セールスポイント		TV		
検査記入欄		キーレス		
AC (不良) なし ルーフ (傷・色褪せ) なし 内装 (ベットの毛) なし 下回りサビ・腐食穴 なし チェックランプなし ハンドルの破れ・ギミ ナビのボタン操作あり		修復歴 有・()		
FW トビ石 傷A フレ 外装 小 A・U A・曲 A・フレ		A キズ U ヘコみサレ B キズヘコシ P 色あせ・ボケ Q ガラスキズ		
内装 ヨゴレ シミ ヤブレ コゲ コゲ穴 オーディオ穴 スレ		W 補修跡 S サビ C 腐食 X 交換車 XX 交換済		
登録No.		名義中		
車体番号 GE6-1161359		月 日 までに名義できる方		
シリアル No.		重量 kg		
長さ cm 幅 cm 高さ cm 最大積重量 kg				