

2008 SUBARU IMPREZA WRX STI		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
GRB	1,994 cc		
YEAR / REG.	MILEAGE		
2008/03	101,704 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
4WD	MT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Blue	Hatchback		
CHASSIS NO.	DIMENSIONS (L X W X H)		
GRB-005690	442 × 180 × 148 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Exterior: Has noticeable scratches and dents. Interior: Has noticeable stains. Repair history: Shows signs of impact near the front or rear end of the frame.			

ORIGINAL JAPANESE AUCTION SHEET

青枠内のグー鑑定/JAAA鑑定証の評価と下記記載の評価は異なります

初年度登録 H20/3月	メーカー スバル	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 インプレッサ	グレード WRX STi			
車種 自家用	型式 GRB	初年式 2000	燃料 ガソリン	内装 B
年 -	月 -	日 -	走行 101,704 km	車台番号 GRB-005690
外装色 紺	カラーNo. ()	リサイクル料 12,360円	販売店 GRB-005690	長さ cm
()	シフト フロア 6 MT	乗車定員 5人	幅 cm	高さ cm

後付品
(保証書・取扱説明書等)

装備
① サルーフ ② ナビ TV ③ キーレス

セールスポイント
バックカメラETC噴霧防止装置 (ESC)/HID・キセノン・ディスプレイ/運転席エアバック/運転席止システム/スマートキー/キーレスエントリー/A B S/助手席エアバック/サイドエアバック衝突安全ボディ/4WD

査定員記入欄

※ダメージレベルに関する注意事項
傷は記号のみ
A: 軽微な傷
B: 軽微な傷
C: 軽微な傷
D: 軽微な傷
E: 軽微な傷
F: 軽微な傷
G: 軽微な傷
H: 軽微な傷
I: 軽微な傷
J: 軽微な傷
K: 軽微な傷
L: 軽微な傷
M: 軽微な傷
N: 軽微な傷
O: 軽微な傷
P: 軽微な傷
Q: 軽微な傷
R: 軽微な傷
S: 軽微な傷
T: 軽微な傷
U: 軽微な傷
V: 軽微な傷
W: 軽微な傷
X: 軽微な傷
Y: 軽微な傷
Z: 軽微な傷

クオリティグレード説明
外装: 気になるようなキズやヘコミがあります。
内装: 気になる汚れ等があります。
修復歴: 骨格部付近の先端付近、または後端付近に衝撃を受けた形跡があります。

車両状態の検閲は、停止状態で実施できる範囲で行っています。