

2008 Mazda MPV 23S		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE LY3P	DISPLACEMENT 2,260 cc		
YEAR / REG. 2008/07	MILEAGE 18,000 km		
DOORS 5	SEATS 8		
TRANSMISSION AT	FUEL Petrol		
STEERING Right	EXTERIOR COLOR White		
BODY TYPE Minivan			
CHASSIS NO. LY3P-208783	DIMENSIONS (L X W X H) 486 × 185 × 169 cm		
SALES POINTS			
Alloy Wheels Back Camera		Power Sliding Doors (Both Sides) (Both... Navigation System	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, exterior minor and light scratches.			

初年度登録		メーカー		ドフ後数		ボディ形状		年価点	
H20 / 7月		マツダ MPV		グレード 23S		ミニバンボックス		9年点	
車種 良車用・その他()		排気量 2300 CC		型式 LY3P		通称 形式		内装 A・B・C	
車検 9年7月		燃料 ガソリン		ディーゼル		検日連号貼(保証書・取扱説明書等)			
走行 18,000 km		シフト フロア 5 AT							
外装色 クリスタルホワイトパールマイカ		カラーNo. G6・AAC・WAG・()		装備品のみにO印を記入					
()		内装色 標準定員 8人		F6 F7 AM サンルフ 革シート					
ハサビ 左・右		ディスター 並行		サイズと料 15,180円 + 預託金		エブリック G6 G7 D7 モーリス			
セールスポイント									
3列シート/C/Dウォークスルー/バックカメラ/TIC/H I D・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/キーレスエントリー/A/B S/助手席エアバック/メモリーナビ他/フルセグTV/衝突安全ボディ/DVD再生/ミュージックプレーヤー接続可/両側電動スライドドア									
検査記入欄									
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ									
修正歴 有。()									
A	文字	U	ヘッパケル	B	文字・ヘッパ	P	黄色セボテ	G	ガラスキズ
W	修繕部	S	サビ	C	腐食	X	交換済	XX	交換済
登録No.	月 日 までは名義である								
車体番号	LY3P-208783								
FW	(トビ)	備A	フレ	外装	小 (コ)・(ロ)	ホイール A・曲	エアロ A・フレ	シリアル No.	
内装	(ニ)	シミ	ヤブレ	コゲ	コガク	オーデイオ	(リ)	車庫	最大積重量