


2008 Mitsubishi Delica D5 Chamonix		OVERALL	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE CV5W	DISPLACEMENT 2,359 cc		
YEAR / REG. 2008/02	MILEAGE 108,510 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. CV5W-0109203	DIMENSIONS (L X W X H) 473 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels Cruise Control Side Camera Navigation System		Power Sliding Doors (Both Sides) (Both... Front Camera Back Camera	
INSPECTOR REPORT			
Glass has a dent and needs repair. Interior has dents, burns, holes, dirt, and tears. Steering wheel has wear. Seats have sagging and tears. End panel is distorted. A/C works fine. Headliner is dirty. Wheels are grade A.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初度登録年月	車名	ドア	形状	グレード	評価点
	20年2月	デリカD5	5W	シャモニー	4WD	3.5
車検	20年4月30日	型式	DBA	CV5W	2400cc	7人
走行	108510 km	冷却	A/C	ガソリン・軽油	MTのみ	速
外装色	黒	内装色	黒	新車保証書	取扱説明書	R券 ¥14,810
注意	後日品	不具合箇所	ガラスのX要ス	シート	コゲ・穴・汚れ・破れ	インパネ
事項	18インチアルミ	タイヤ	フロント・リア	8分		
検査員記入	ガラス	シート	コゲ	穴	汚れ	破れ
長さ	幅	高さ	重量	kg		



小A 小U