

2008 Nissan Cube Rider		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-YZ11	DISPLACEMENT 1,498 cc		
YEAR / REG. 2008/02	MILEAGE 82,255 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Station Wagon		
CHASSIS NO. YZ11-083801	DIMENSIONS (L X W X H) 379 × 167 × 164 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Scratches on the underside of the front bumper, front bumper misaligned on the left, paint cracks on rear U2 section, AC not cooling.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H20/2月	メーカー 日産	ドア枚数 5	ボディ形状 ステーションワゴン	評価点 4
車名 キューブ	グレード ライダー	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 1500 CC	型式 DBA-YZ11	通称 形式	内装 A・B・C
車検 9年3月	燃料 ガソリン	ディーゼル	検出過剰品 (保証書・取扱説明書 等)	
走行 82,255マイル	シフト ハイブリッド	AT		
外装色 パールホワイト	カラーNo. ()	エアコン AG・AG・WAG・()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 ()人	PS	サンルーフ
ハンド 左・右	輸入 区分	リサイクル料 10,570円・預託料	エアバック	ナビ
セールスポイント 希少車		A2 A3 U2 修復歴 有・無		
検査記入欄 フロントバンパー下面傷有 フロントバンパー左ズレ有 リアU2部分ペイントヒビ有 AC冷えず		A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換歴 XX 交換済 登録No. 月 日 までに名実できる方 車体 番号 YZ11-083801 FW トピ石 傷A フレ 外装 小 大 車検 車検 内装 ヨゴレ シシ ヤブレ コガ コガ穴 オーディオ穴 スレ		
		長さ cm 高さ cm 最大積載量 Kg		