

2008 Nissan Pino 660 S		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-HC24S		DISPLACEMENT 658 cc	
YEAR / REG. 2008/07		MILEAGE 74,000 km	
DOORS 5		SEATS 4	
DRIVETRAIN 2WD (FF)		TRANSMISSION AT	
FUEL Petrol		STEERING Right	
EXTERIOR COLOR White		BODY TYPE Hatchback	
CHASSIS NO. HC24S-600945		DIMENSIONS (L X W X H) 340 × 148 × 150 cm	
INSPECTOR REPORT			
Steering wheel wear, dirty interior, minor underbody rust, minor scratches, dents, paint fade/peeling, door mirror scratches, seat wear and scuffs, mirror scratches, general fade, driver's side mirror paint fade, console blemishes.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H20/7月		メーカー 日産		ドア枚数 5		ボディ形状 コンパクト/ハッチバック		評価点 R																					
車名 ピノ		グレード 660 S CDオーディオ エアパック ABS 300		駆動方式 2WD 4WD																									
車歴 自家用・その他 ()	積載量 660	型式 DBA-HC24S	通称 型式	内装 A・B・C																									
車検 - - 年 / 月 / 日	燃料 ガソリン	ディーゼル	後日選り品 (保証書・取扱説明書等)																										
走行 74,000 km	シフト フロア 3	AT																											
外装色 ベージュ	カラーNo. ()	エアコン QD・AAC・WAG・()	装備品のみ O印 を記入																										
内装色 ()	乗車定員 4 人	PS	PS	AW	サンルーフ	革シート																							
ハンドル 左・右	輸入 区分	ディーラー・並行	リサイクル料 8,690 円	預託料	エアパック	ABS	ナビ	TV	キーレス																				
セールスポイント A B S / 運転席エアバック/助手席エアバック/CD																													
検査記入欄 ハンドルすれ有 ルーム内汚れ 下廻りサビS 小キズ有へこみ有 Pアセ有ハゲ ドアミラーキズ シートへたり スレ ミラーキズ アセ DミラーAP あせ コンソールB P			修復歴 車検 <table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>へこみ/サレ</td><td>B</td><td>キズへこみ</td><td>P</td><td>色あせ/ボケ</td><td>Q</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table> 登録No. 月 日 までに名変できる方 車体番号 HC24S-600945							A	キズ	U	へこみ/サレ	B	キズへこみ	P	色あせ/ボケ	Q	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	へこみ/サレ	B	キズへこみ	P	色あせ/ボケ	Q	ガラスキズ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
PW	トピ石	傷A	フレ	外装	小	ホイール	エアロ	シリアルNo.																					
内装	ヨゴレ	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	長さ	幅																				
							高さ	最大積載量	Kg																				