

2008 Toyota REGIUS ACE VAN Super GL		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ADF-KDH201V	2,982 cc		
YEAR / REG.	MILEAGE		
2008/05	148,272 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Diesel	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
KDH201-0023961	470 × 170 × 198 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Rear panel dent, multiple dents on rear roof, oil leak around engine, screw holes on console and interior trim, glue marks on dashboard, glue on interior trim, right mirror missing.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H20/5月	メーカー トヨタ	ドア枚数 5	ボディ形状 バン	評価点 3
車名 レジアスエースバン	グレード スーパーGL	駆動方式 2WD 4WD		
車種 自家用・その他()	排気量 2980 CC	型式 ADF-KDH201V	通称 A・B・C	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン ハイブリッド()	シフト AT	検出通り品() 取替() 修理() 等()	
走行 148,272 km	インパネ	AT		
外装色 ブラック	カラーNo. 209	エアコン AG・AAG・AG・()	装備品のみ ORP を記入	
()	内装色	乗車定員 5 人	PS 2WD サンルーフ 車シート	
左・右 左・右	ディーラー ディーラー	走行 10,840 km	オプション エブリック	ナビ TV キーレス
セールスポイント				
ナビ インテリアパネル コンビH/シフトノブ シートカバー 社外ハイマウント 社外AW(17インチ) ホワイトレター				
検査記入欄				
R/パネル ルーフ エンジンオイル漏れ コンソール・内装ビス穴 ダッシュノリ跡 内装ノリ跡 Rミラー穴				
A キズ U ヘコみサレ B キズヘコみ P 色あせ・ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 まで(名義できる方)				
車体番号 KDH201-0023961				
FW トビ石 ⑤ フレ 外装 小 ⑤ ⑥ ホイル A・曲 A・フレ				
内装 ⑤ シス ヤブレ コガ コガ穴 オーディ穴 ⑤				
長さ 469 cm 幅 169 cm 高さ 198 cm 最大積載量 1000 kg				