

2009 Daihatsu Boon X4 High Grade Pack TB 4WD		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE M312S	DISPLACEMENT 936 cc		
YEAR / REG. 2009/07	MILEAGE 106,460 km		
DOORS 5	SEATS 5		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. M312S-0000792	DIMENSIONS (L X W X H) 363 × 167 × 155 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Steering wheel scuff (with cover). Interior has odor. Minor scratches/dents on door mirror and exterior wheels. Exterior paint damage (P7C). Underbody shows rust/corrosion, a small dot/dent, and paint damage. End panel has rust/corrosion and bodywork. Oil seepage present. Steps, general areas, and S-tire house interior show rust/corrosion.			

ORIGINAL JAPANESE AUCTION SHEET

出品番号	初度登録年月	車名	ドア 形状	グレード	評価点
	21年7月	ブーン	5H	ボーン 4WD	3.5
車検	年 月 日	型式	AT	新正モリンドル	外装
走行	106460	ABM312S	5速	外装15インチホイール ETC	B
外装色	白	色番	AC	PS	内装
内装色		ガリ	軽油	AW	B
新車保証書	取扱説明書	R券	9,510	SR	純正のみ
注意	後日品	名変期限	月 日迄	カワ	丸印
事項	タイヤ4本6.9分山	車検	M312S-0000792	AB	
検査員記入	ガラス	4-X要ス	シート	4-X要ス	
11インチホイール	車内ヤニ	177-A	外装177-A	外装177-A	
下体リウス	エドワーズ	エドワーズ	エドワーズ	エドワーズ	
エドワーズ	エドワーズ	エドワーズ	エドワーズ	エドワーズ	
長さ	cm	幅	cm	高さ	cm
					kg