

2009 Daihatsu COPEN 660 Active Top		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE ABA-L880K	DISPLACEMENT 659 cc		
YEAR / REG. 2009/11	MILEAGE 120,000 km		
DOORS 2	SEATS 2		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Convertible		
CHASSIS NO. L880K-0051804	DIMENSIONS (L X W X H) 340 × 148 × 125 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Abnormal engine noise, engine oil leak, aftermarket tail lights, aftermarket stereo faulty.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21/11月	メーカー ダイハツ	ドア枚数 2	ボディ構造 オープン(カブリオーレ・コンバーチブル)	評価点 4
車名 コペン	グレード 660 アクティブトップ HID・キーレス	駆動方式 2WD 4WD	車種区分 2WD 4WD	
車種 自家用・その他()	排気量 660 cc	型式 ABA-L880K	通称 A・C	内装 A・C
車検 4年11月	燃料 ガソリン	ディーゼル	後日送付品(保証書・取扱説明書等)	
走行 120,000 km	シフト フロア 4 AT	エアコン	新車のみ O印 を記入	
外装色 パールホワイト	カラーNo. ()	内装色 ()	乗車定員 2人	オプション サンルーフ 車シート
ハンド 左・右	輸入 区分	ディーラー 並行	リサイクル料 9,170円・預託金	オプション ナビ TV
セールスポイント キーレスエントリー/A B S /運転席エアバック/助手席エアバック/M T モード付き		修復歴 有・無		
検査記入欄 エンジン廻り異音 エンジン廻りオイル漏れ 社外テール 社外ステレオ不良		A キズ U ヘビイサレ B キズ・ヘビイ C 色あせ・サケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換席 XX 交換席 登録No. 月 日 までに名変できる方 名変中 車検番号 L880K-0051804		
FW トビ	備A シ	ワレ ヤ	外装 小 A・C A・曲 A・ワレ	シリアル No.
内装 ヨゴレ	シミ	ヤブレ	コガ コガ穴 オーディオ穴 スレ	長さ cm 幅 cm 高さ cm 最大積重量 kg