


2009 Daihatsu Esse 660 D Selection		OVERALL	
		3	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-L235S	DISPLACEMENT 658 cc		
YEAR / REG. 2009/02	MILEAGE 77,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Hatchback		
CHASSIS NO. L235S-1033488	DIMENSIONS (L X W X H) 340 × 148 × 147 cm		
INSPECTOR REPORT			
Underbody rust/corrosion (S-grade), large headliner stains, large carpet burns, worn/sagging seats, medium scratches on door trim, scratches on cargo area trim, steering wheel wear, console scratches, medium burn holes on seats, aftermarket wheels, exterior stains, exterior color fading, hood removed/reinstalled.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21 / 2月	メーカー ダイハツ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 3
車名 エッセ	グレード 660 D セレクション 5速マ ニュアル/ エアコンクー ラー	駆動区分 2WD 4WD		
車種 自家用 ・ その他 ()	排気量 660 cc	型式 DBA-L235S	通称 型式	内装 A ・ B (C)
燃料 ガソリン	ディーゼル	後日送り品 (保証書 ・ 取扱説明書 等)		
走行 77,000 km	マイル フロア 5 MT			
外装色 ホワイト	カラーNo. ()	装備品のみ O印 を記入		
内装色 ()	乗車定員 4 人			
左・右 左・右	輸入 区分	ディーラー ・ 並行	リサイクル料 8,340円	保証書 ・ 取扱書
セールスポイント 運転席エアバック/助手席エアバック/D				
検査記入欄 下廻りS有天張汚れ大カーペット焦げ大シートへたり有 ドア内張傷中荷安全張傷有ハンドルすれ「コンソール傷 有シート焦げ穴中備考外AW外装しみ外装色あせ ボンネット脱着		修復歴 有 (C)		
登録No. L235S-1033488		名義中 月 日 まで名義できる方		
車体 番号		シリアル No.		
PW トビ石	備A A ・ U	ワレ A ・ 曲	外装 A ・ ワレ	小 A ・ 曲
内装 ヨゴレ	シミ	ヤブレ	コガ コガ穴	オーディオ穴 スレ
長さ cm	幅 cm	高さ cm	最大積載量 Kg	