

2009 Honda Accord Tourer 24E		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-CW2	DISPLACEMENT 2,354 cc		
YEAR / REG. 2009	MILEAGE 40,500 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Station Wagon		
CHASSIS NO. CW2-1001873	DIMENSIONS (L X W X H) 475 × 184 × 147 cm		
SALES POINTS			
Alloy Wheels Cruise Control		Roof Rails Navigation System	
INSPECTOR REPORT			
Interior/Exterior AU grade. Interior has hair dirt and burn holes on seats. AC is not working, and the headliner is sagging. Underbody shows rust, and alloy wheels have scratches. Rear spoiler paint is faded.			

ORIGINAL JAPANESE AUCTION SHEET

21	アコード ツアラー			5・W	24E			4	
型 式		排 気 量	燃 料	車 種	定員(最大)	積載量(最大)	輸 入 車		
DBA	CW2	2,400 _{CC}	ガソリン	自家用	5 名	Kg			
ミッション	エアコン	カラーNo.	外 装 色		装 備			保証書	取扱説明書
FAT	AAC	NH743M	グレー		PS	PW	17B	ABS	有
					ナビ	TV		アルミ	
走行距離		車 検	登録ナンバー		注 記・装 備			車 台 番 号	預託金
40,500 _{km}		年 月						CW2-1001873	13,840 _円
セールスポイント			特記事項・不具合箇所						
Bモニター ルーフレール			内外装AU ルーム内毛汚れ、シートが汚 AC不良、天張タルミ 下廻りサビ、ABSが Rスボイラーがアセ						
注 意 事 項									
									