


2009 Honda ACTY TRUCK SDX		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE GBD-HA7	DISPLACEMENT 656 cc		
YEAR / REG. 2009/09	MILEAGE 85,657 km		
DOORS 2	SEATS 2		
DRIVETRAIN 4WD	TRANSMISSION MT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Kei		
CHASSIS NO. HA7-1729763	DIMENSIONS (L X W X H) 340 × 148 × 175 cm		
INSPECTOR REPORT			
Cargo bed: minor scratches, dents, rust. Undercarriage: rust. Driver's seat: worn upholstery. Left step: paint repair.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21	メーカー ホンダ	ドア枚数 2	ボディ形状 軽四	評価点 R
9月	車名 アクティトラック	グレード SDX	駆動区分 2WD 4WD	
車歴 自家用・その他 ()	排気量 660	型式 GBD-HA7	通称 型式	内装 A・B・C
車検 9年9月 / 抹消	燃料 ガソリン	ディーゼル	後日送り品 (保証書・防犯カメラ等)	
走行 85,657マイル	シフト ハイブリッド	フロア 5 MT	スペアキー	
外装色 ホワイト	カラーNo. (NH578)	エアコン A・B・AAG・WAG・()	新備品のみ O印 を記入	
()	色車検は()内に 「色検」と記入	乗車定員 2人	P	PW
ハンド 左・右	輸入 区分	ディーラー・並行	リサイクル料 5,970円・預託無	エアパック
セールスポイント ★ユーザー買取車★4WD★5速ミッション★エアコン★ パワステ★三方開				
特記事項 ★展示用内外装仕上げ済み★		修復歴 ③・無		
検査記入欄 荷台 A・U・S 下回りS 運転席シートフチャブレ 左ステップBP		A キズ U ヘコみ・凹み B キズ・ヘコみ P 色あせ・剥落 G ガラスキズ W 補修跡 S サビ C 腐食 X 交換箇所 XX 交換所 登録No. 月 日 までに名義できる方 車体 番号 HA7-1729763 シリアル No.		
PW トド石	備A	フレ	外装	小
内装	ヨコレ	シミ	ヤブレ	コゲ
コゲ穴	オーディ穴	スレ	長さ	339 cm
幅	147 cm	高さ	174 cm	最大積載量 Kg