


2009 Honda Crossroad 5D 1.8 18L X Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RT1	DISPLACEMENT 1,799 cc		
YEAR / REG. 2009/12	MILEAGE 81,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE SUV		
CHASSIS NO. RT1-1000487	DIMENSIONS (L X W X H) 429 × 176 × 167 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Uneven paint color change, rust on undercarriage.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21 / 12月		メーカー ホンダ		ドア枚数 5	ボディ形状 SUV/クロカン		評価点 4																				
車名 クロスロード		グレード 1.8 18L Xパッケージアルミホイール 新品ホワイトレタータイヤ		駆動区分 2WD 4WD																							
車種 自家用・その他 ()	排気量 1800 cc	型式 DBA-RT1	通称 型式	内装 A・⑤・C																							
車検 - - 年 / 月	燃料 ガソリン	ディーゼル ハイブリッド ()	後日送り品 (保証書・取扱説明書 等)																								
走行 81,000 km	シフト インパネ 5 AT																										
外装色 ベージュ	カラーNo. ()	エアコン AG・QG・WAG・()	新着品のみ O印 を記入																								
(色替)	内装色 ()	乗車定員 7 人	PS	PS	AW	サンルーフ	革シート																				
ハンドル 左・(右)	輸入 区分	ディーラー ・ 並行	ナシ	13,470 円	・ 預託金	エブリック	ナビ TV モーリス																				
セールスポイント 全塗装・新品タイヤ&アルミホイール・キーレスキー・社外ナビ・フルセグTV・Bモニター																											
検査記入欄 色替えムラ有・下回りサビ			修復歴 有・⑤																								
			<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘコみ/サレ</td><td>B</td><td>キズ/ヘコみ</td><td>P</td><td>色あせ/ボケ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td></tr></table>					A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	G	ガラスキズ																		
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																		
			登録No. 名義中 月 日 までに名義できる方																								
			車検 番号 RT1-1000487																								
FW (トビ)	備A	ワレ	外装 ①・②	ホイール A・曲	エアロ A・ワレ	シリアル No.																					
内装 (ヨシ)	シミ	ヤブレ	コガ	コガ穴	オーディオ穴	スレ	車輪 最大重量 cm cm cm Kg																				