

2009 Honda INSIGHT 1.3 L		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZE2	DISPLACEMENT 1,339 cc		
YEAR / REG. 2009/09	MILEAGE 88,000 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Hatchback		
CHASSIS NO. ZE2-1164422	DIMENSIONS (L X W X H) 439 × 170 × 143 cm		
SALES POINTS			
Navigation System			
INSPECTOR REPORT			
Right fender XX, right front inside panel distorted			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21/9月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 R
車名 インサイト	グレード 1.3Lキーレスエントリー/ETC/メモリーナビ/Blue	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 1300 cc	型式 DAA-ZE2	通称 A・⑨・C	
年 88	月 00	日 00	走行 88,000 km	燃料 ガソリン
シフト フロア	CVT	後日選り品 (保証書・取扱説明書 等)		
外装色 クリスタルブラック・パール	カラーNo. ()	エアコン ()	新車のみ O印 を記入	
内装色 ()	乗車定員 5 人	PS ()	AW ()	サンルーフ ()
ハンド ()	左・右 ()	11,460 円	エアロック ()	スー ()
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/メモリーナビ他/フルセグTV/ETC/アイドリングストップ/盗難防止システム/H I D ・キセノン・ディスプレイチャージ				
検査記入欄				
右フェンダーXX				
右フロントインサイドパネル歪				
修復歴				
A キズ U ヘビイサレ B キズ・ヘビサ C 色あせ・サケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換部 XX 交換所				
登録No. 月 日 までに名変できる方				
名変中				
ZE2-1164422				
FW トビ石 備A フレ 外装 小 赤イロ エアロ シリアル No.				
内装 ヨゴレ シミ ヤブレ コガ コガ穴 オーディオ穴 スレ				
長さ cm	幅 cm	高さ cm	最大積重量 Kg	