

2009 Honda INSIGHT G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ZE2	1,339 cc		
YEAR / REG.	MILEAGE		
2009/08	42,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Other	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZE2-1153980	439 × 170 × 143 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has small and light scratches. AA auction grade 4. Lower support is distorted.			

初年度登録		メーカー		ドア枚数		ボディ形状		評価点																																									
H21 / 8月		ホンダ インサイト		グレード		ゼダン		4																																									
車種 自動車・その他 ()		積重量 1300 CC		型式 ZE2		運転形式		内装 A・B・C																																									
車検 8年8月		抹消 燃料 ガソリン シフト ハンドレック		ディーゼル		使用履歴 (保証書・取扱説明書等)																																											
走行 42,000 km		マイル フロア AT																																															
外装色 ポリッシュメタルメタリック		カラーNo. エアカン		()		新製品のみ O印 を記入																																											
()		内装色 標準定員 5人																																															
パワステ		左・右		ディフター		走行		11,460円 + 国庫税																																									
セールスポイント		CD/バックカメラ/TC/運転席エアバック/盗難防止システム/キーレスエントリー/A B S /助手席エアバック/H D Dナビ/ワンセグTV/衝突安全ボディ/DVD再生																																															
検査記入欄																																																	
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ □アササポート窓口		<table border="1"> <tr> <th>A</th><th>キズ</th><th>U</th><th>ヘコみ/サレ</th><th>B</th><th>キズ/ヘコみ</th><th>D</th><th>傷/凹み/ボロボロ</th><th>G</th><th>ガラスキズ</th></tr> <tr> <th>W</th><th>腐食/錆</th><th>S</th><th>サビ</th><th>C</th><th>腐食</th><th>X</th><th>交換済</th><th>XX</th><th>交換済</th></tr> <tr> <td colspan="2">登録地</td><td colspan="2">月</td><td colspan="2">日</td><td colspan="4">まで(名義変更あり)</td></tr> <tr> <td colspan="2">車体番号</td><td colspan="8">ZE2-1153980</td></tr> </table>								A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	D	傷/凹み/ボロボロ	G	ガラスキズ	W	腐食/錆	S	サビ	C	腐食	X	交換済	XX	交換済	登録地		月		日		まで(名義変更あり)				車体番号		ZE2-1153980							
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	D	傷/凹み/ボロボロ	G	ガラスキズ																																								
W	腐食/錆	S	サビ	C	腐食	X	交換済	XX	交換済																																								
登録地		月		日		まで(名義変更あり)																																											
車体番号		ZE2-1153980																																															
FW		トピ		小		ホイル		エアロ																																									
内装		シロ		ヤブ		コガ		オデイ																																									