

2009 Honda INSIGHT G		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
ZE2	1,339 cc		
YEAR / REG.	MILEAGE		
2009/06	31,000 km		
DOORS	SEATS		
5	5		
DRIVETRAIN	TRANSMISSION		
2WD (FF)	AT		
FUEL	STEERING		
Hybrid (Petrol)	Right		
EXTERIOR COLOR	BODY TYPE		
Silver	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
ZE2-1136184	439 × 170 × 143 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior has scratches and dirt. Seats show scuffs and wrinkles. Exterior has minor and light scratches. The pillar belt is pinched.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21/6月	メーカー ホンダ	ドア枚数 5	ボディ形状 セダン	評価点 4
車名 インサイト	グレード G	駆動方式 2WD	4WD	
車種 自家用・その他 ()	排気量 1300 CC	型式 ZE2	通称 型式	内装 A・B・C
車検 - - 年 月 / 日	燃料 ガソリン	ディーゼル	検出通り品 (保証書・取扱説明書 等)	
走行 31,000 km	シフト フロア	AT		
外装色 アプラスターシルバーメタリック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 5 人	PS	AW
左・右 左・右	ディーラー ディーラー	走行 11,460 km	エアバッグ	サンルーフ
セールスポイント				
CD/バックカメラ/ETC/運転席エアバック/盗難防止システム/キーレスエントリー/ABS/助手席エアバック/HDDナビ/ワンセグTV/衝突安全ボディ/VDV再生				
検査記入欄				
内装キズ、汚れ シートスレ、シワ 外装小キズ、薄キズ AA評価4点仕入れ ピラーベルト抜き込み				
車検 有・無				
修理歴 有・無				
A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ				
W 補修跡 S サイズ C 腐食 X 交換済 YX 交換済				
登録No. 月 日 までにも変更できる方				
車体No. ZE2-1136184				
FW (トビ) 傷A フレ 小 (B・C) ホイル A・曲 A・フレ				
内装 (ゴ) シス ヤブレ コグ コグ穴 オーディオ穴 (D)				
長さ 幅 高さ 最大積重量				
cm cm cm Kg				