

2009 Honda Stream RSZ HDD Navi Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE RN8	DISPLACEMENT 1,997 cc		
YEAR / REG. 2009/07	MILEAGE 46,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. RN8-3100099	DIMENSIONS (L X W X H) 457 × 170 × 155 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Interior scratches and dirt, seat scuffs and wrinkles, minor exterior and light scratches, AA grade 4, missing emblem			

ORIGINAL JAPANESE AUCTION SHEET

年式	7月	メーカー	ホンダ	ドア枚数	5	ボディ形状	ミニバンワンボックス	評価点	4
車名	ストリーム	グレード	RSZ HDDナビパッケージ	駆動方式	2WD	4WD			
車種	自家用・その他	排気量	2000 cc	型式	RN8	燃費		A・B・C	
年	-	月	-	燃料	ガソリン	ディーゼル		後日選り品	保証書・取扱説明書等
走行	46,000	マイル	インパネ	AT					
外装色	プレミアムホワイトパール	カラーNo.	エアコン	Qd・AAG・WAG				新車品のみ O印 を記入	
内装色								サンルーフ	高シート
小	左・右	乗入	ディーラー	走行	12,300円	販売額	エアロック	TV	ス
セールスポイント									
3列シート/ETC/HID・キセノン・ディスチャージ/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/A B S /助手席エアバック/メモリーナビ他/衝突安全ボディ									
検査記入欄									
内装キズ、汚れ シートスレ、シワ 外装キズ、薄キズ AA評価4点仕入れ エンブレム欠品									
修復歴									
有・無									
A	キズ	U	ヘコみ/サレ	B	キズ/ヘコみ	P	色あせ/ボケ	Q	ガラスキズ
W	腐蝕跡	S	サビ	C	腐食	X	交換済	XX	交換済
名義中									
月 日 までに名義できる方									
車体番号 RN8-3100099									
FW	トランス	機A	フレ	外装	小	ホイール	エアロ	シリアル	
内装	シシ	ヤブレ	コガ	コガ	オーディオ	取	取	取	取