

2009 MercedesBenz S-CLASS S550 Long		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE			
221171	DISPLACEMENT		
	5,461 cc		
YEAR / REG.	MILEAGE		
2009/03	110,860 km		
DOORS	SEATS		
4	5		
DRIVETRAIN	TRANSMISSION		
2WD (FR)	AT		
FUEL	STEERING		
Petrol	Left		
EXTERIOR COLOR	BODY TYPE		
Silver	Sedan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
WDD2211711A227352	521 × 187 × 149 cm		
SALES POINTS			
Alloy Wheels		Sunroof	
Power Seats (Front)		Leather Seats (Leather)	
Cruise Control		Back Camera	
Navigation System		harman/kardon Sound System	
INSPECTOR REPORT			
Glass has stone chips and a crack. Seats are dirty, with burn marks, holes, cuts, tears, wrinkles, and wear. The steering wheel is worn. Interior trim is deteriorated. Door molding is detached/missing. The air suspension has an air leak. The undercarriage shows scratches/impacts. Chrome is dull. Oil seepage is present.			

[illegible]