


2009 Mitsubishi DELICA D:5 G Power Package		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-CV5W	DISPLACEMENT 2,359 cc		
YEAR / REG. 2009/09	MILEAGE 118,000 km		
DOORS 5	SEATS 7		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR White	BODY TYPE Minivan		
CHASSIS NO. CV5W-0307820	DIMENSIONS (L X W X H) 473 × 179 × 187 cm		
SALES POINTS			
Alloy Wheels Navigation System		Cruise Control	
INSPECTOR REPORT			
Minor rust on undercarriage			

ORIGINAL JAPANESE AUCTION SHEET

H21/9月		三菱		5	ミニバンワンボックス		4																				
車種		2400		DBA-CV5W	A・B・C																						
年		月		日																							
走行		118,000		マイル		AT																					
外装色		パールII		内装色		7人																					
左・前		ディーラー		走行		14,810円																					
セールスポイント		4WD クルーズコントロール パドルシフト 両側電動Sドア HDDナビ F/S/Bカメラ ETC スマートキー AW18																									
検査記入欄		下回りサビ小		<table border="1"> <tr> <td>A</td><td>キズ</td><td>U</td><td>ヘビイサレ</td><td>B</td><td>キズヘビ</td><td>P</td><td>色あせサケ</td><td>G</td><td>ガラスキズ</td> </tr> <tr> <td>W</td><td>補修跡</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換済</td><td>XX</td><td>交換済</td> </tr> </table>				A	キズ	U	ヘビイサレ	B	キズヘビ	P	色あせサケ	G	ガラスキズ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	キズ	U	ヘビイサレ	B	キズヘビ	P	色あせサケ	G	ガラスキズ																		
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																		
FW		H21		車A		ワレ																					
内装		ヨゴレ		シミ		ヤブレ																					
外装		小		ホイル		エアロ																					
車輪		473cm		179cm		187cm																					