

2009 Mitsubishi Delica D5 Chamonix		OVERALL	
		3.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE	DISPLACEMENT		
CV5W	2,359 cc		
YEAR / REG.	MILEAGE		
2009/04	138,540 km		
DOORS	SEATS		
5	7		
DRIVETRAIN	TRANSMISSION		
4WD	AT		
FUEL	STEERING		
Petrol	Right		
EXTERIOR COLOR	BODY TYPE		
Black	Minivan		
CHASSIS NO.	DIMENSIONS (L X W X H)		
CV5W-0210537	473 × 180 × 187 cm		
SALES POINTS			
Alloy Wheels		Power Sliding Doors (Both Sides) (Both...	
Cruise Control		Front Camera	
Side Camera		Back Camera	
Navigation System			
INSPECTOR REPORT			
Glass has minor scratches, with some areas requiring repair. Seats show minor wear, burn marks, holes, stains, and tears. The steering wheel and shift panel have peeling/fading. The roof has light scratches and clear coat peeling. Wheels have minor scratches, gouges, and stains. The undercarriage shows paint damage and corrosion (AUVc). The muffler has repair marks. Exterior paint is faded and peeling.			

出品番号	初年度登録年月	車名	ドア	形状	グレード	評価点	
	21年4月	デリカダ5	5W	シャボニ-	4WD	3.5	
車種	車庫()	型式	ABA-CV5W	排気量	2400cc	定員	
						7人	
車検	年	月	日	フロア	AD	側面制パワースライドドア	
走行	十	万	千	百	十	一	MTのみ
	1	3	8	5	4	0	連
外装色	馬	色番	車は色番と記入	冷房	材料	AAC	カラー
内装色	馬	外装カラーNo.	X24	輸入車	モデル年式	年・不明	D車・並
							右・左H
新車保証書	取扱説明書	R券	¥14810	名	変期限	月	日迄
後日品【	不具合箇所等	白ラインAC	クルーズコントロール	コンビハンドル	4本コイルスプリング	スカスカ	
注意事項							
検査員記入	ガラス	④ X要ス	室内	④ コゲ・穴・汚	④ 破れ		
11ポルハグ	51ポルハグ						
ル・フワリ・キ・11ポルハグ							
土イNA	天経ハグ						
下組黒P	AVSC						
222	新ハグ						
外装Pセハグ							
長さ	幅	高さ	重量	kg			
cm	cm	cm	cm	kg			