


2009 Nissan NOTE 15X		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE E11	DISPLACEMENT 1,498 cc		
YEAR / REG. 2009/12	MILEAGE 22,614 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Gray	BODY TYPE Hatchback		
CHASSIS NO. E11-386395	DIMENSIONS (L X W X H) 402 × 169 × 154 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
JAAA appraised: Exterior 4, Interior 5. Minor touch-up repairs, trim wear, driver's seat minor wrinkles. Wheel scuffs (LF/RR). All tires have cracks. Right front door edge scratch.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H21/12月	メーカー 日産	ドア枚数 5	ボディ形状 コンパクト/ハッチバック	評価点 4.5
車名 ノート	グレード 15X	駆動方式 2WD 4WD		
車種 自家用・その他 ()	排気量 1500 CC	型式 E11	通称 型式	内装 A・B・C
車検 10年8月	燃料 ガソリン	ディーゼル	後付選り品 (保証書・取扱説明書 等)	
走行 22,614 km	シフト フロア	AT		
外装色 グレー	カラーNo. ()	エアコン A・A・G・W・A・G・ ()	装備品のみ O印 を記入	
()	内装色 ()	乗車定員 5 人	PS	サンルーフ
左・右 左・右	ディーラー ディーラー	走行 10,640 km	エアロック	ABS
セールスポイント ワンオーナー/CD/ETC/運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/HDDナビ/フルセグTV/衝突安全ボディ/アイドリングストップ/DVD再生				
検査記入欄 JAAA鑑定 外装★4内装★5 タッチアップ補修跡 トリムシワスレ傷 D席シワスレ小 ホイル割れ傷(左F/右R)全タイヤヒビ切れ 右Fドアエッジ傷				
				
修復歴 有・無 ()				
A キズ U ヘコみ/サレ B キズ/ヘコみ P 色あせ/ボケ Q ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済				
登録No. 月 日 までにも名義できる方 名義中				
車体番号 E11-386395				
シリアルNo.				
FW	トビ	傷A	フレ	外装
内装	ヨゴレ	シミ	ヤブレ	コガ
小	A・U	ホイル	A・曲	エアロ
スレ	オーディ	穴	スレ	
長さ	幅	高さ	最大積載量	
cm	cm	cm	Kg	