

2009 Suzuki Alto Lapin T		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE HE22S	DISPLACEMENT 658 cc		
YEAR / REG. 2009/02	MILEAGE 125,000 km		
DOORS 5	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pink	BODY TYPE Kei		
CHASSIS NO. HE22S-801431	DIMENSIONS (L X W X H) 340 × 148 × 151 cm		
SALES POINTS			
Alloy Wheels		Navigation System	
INSPECTOR REPORT			
Front accident repair history. Interior has scratches and scuffs. Core support, right front inner panel, and part of the right side member have been repaired or replaced. Heater is weak. Various scratches, dents, repairs, and paint fading.			

初年登録費		メーカー スズキ		ドアク数 5		ボディ形状 軽四		評価点 R																					
H21 / 2月		車名 アルトラパン		グレード T		駆動方式 4WD																							
車種 自家用・その他()		排気量 660 CC		型式 HE22S		運転形式		内装 A・⑤・C																					
車検 10年2月 / 抜拭		燃料 ガソリン		ディーゼル ハイブリッド()		償目通り品 (保証書・取扱説明書等)																							
走行 1万2千5百00マイル		シフト フロア AT																											
外装色 ピンクM カラーNo.		エディション Qd・AGD・WAG・()		装備品の目 O印 を記入																									
()		内装色		標準定員 4人		☐ PS ☐ ES ☐ AS ☐ サンルーフ ☐ 革シート																							
ハシレ 左・輸入ディーラー・走行		リサイクル料		9,870円・買取額		☒ エアパック ☒ ABS ☒ CD ☒ TV ☒ モーニング																							
セールスポイント																													
CD/ETC/運転席エアバック/スマートキー/キーレスエントリー/A B S/助手席エアバック/メモリーナビゲーション/セグTV/ターボ				修復歴 ☒ 無																									
検査記入欄				<table border="1"> <thead> <tr> <th>A</th> <th>クズ</th> <th>U</th> <th>ヘルスオサバ</th> <th>B</th> <th>クズ/ヘルスP</th> <th>H</th> <th>色あせ/変色</th> <th>G</th> <th>ガラスキ</th> </tr> </thead> <tbody> <tr> <td>W</td> <td>補修跡</td> <td>S</td> <td>サビ</td> <td>C</td> <td>腐食</td> <td>X</td> <td>交換済</td> <td>XX</td> <td>交換済</td> </tr> </tbody> </table>						A	クズ	U	ヘルスオサバ	B	クズ/ヘルスP	H	色あせ/変色	G	ガラスキ	W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済
A	クズ	U	ヘルスオサバ	B	クズ/ヘルスP	H	色あせ/変色	G	ガラスキ																				
W	補修跡	S	サビ	C	腐食	X	交換済	XX	交換済																				
F-標準型 ルーム内スレープ コアサブストXX 非FインナーXX 右サイドメンバー1部XX ヒーター暖し 後半5区画ショウアップ				登録日 年 月 日 までに変更できる。																									
PW トビ石 備A ワレ 内装 ヨゴレ シミ ヤブレ コガ コガ スコグス オーディオAS				事故番号 HE22S-801431 シリアル No. 車両 重量 全高 最大積載量																									