

2009 Toyota Hiace Wagon GL		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE TRH219W	DISPLACEMENT 2,693 cc		
YEAR / REG. 2009/12	MILEAGE 108,281 km		
DOORS 4	SEATS 10		
DRIVETRAIN 4WD	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Black	BODY TYPE Minivan		
CHASSIS NO. TRH219-0009527	DIMENSIONS (L X W X H) 484 × 188 × 210 cm		
SALES POINTS			
Back Camera		Navigation System	
INSPECTOR REPORT			
Interior has scuffs, dirt, and scratches. Carpet is torn. Cargo area has modifications and screw holes. Various scratches and dents.			

ORIGINAL JAPANESE AUCTION SHEET

前年度登録 H21/12月	メーカー トヨタ	ドア枚数 4	ボディ形状 バン	評価点 4
車名 ハイエースワゴン	グレード GL	駆動区分 2WD 4WD		
車種 自家用・その他 ()	排気量 2700 CC	型式 TRH219W	通称 型式	内装 A・B
車検 - - 年 月 / 日	燃料 ガソリン ハイブリッド ()	ディーゼル ()	検閲通り品 (保証書・取扱説明書 等)	
走行 108,281 km	シフト AT			
外装色 ブラック	カラーNo. ()	エアコン Qd・AAG・WAG・()	装備品のみ ORP を記入	
()	内装色 ()	乗車定員 ()	PS	PW
左・右 ()	ディーラー ()	走行 ()	エアバック	ABS
15,250円		リサイクル料	ナビ	TV
セールスポイント アルパインナビ		修復歴 有 ()		
特記事項 リアカメラ映らない		A1 AU1 147部 U1 多 A2 U3 AU2		
検査記入欄 ルーム内スレ汚れキズ カーペット破れ 荷室加工有・ビス穴 各キズ凹み		A キズ U ヘッドライト B キズ・ヘッド C 色あせ・ボケ D ガラスキズ W 補修跡 S サイズ C 腐食 X 交換済 XX 交換済 登録No. 月 日 までにも名実できる方 名実中 車体 番号 TRH219-0009527 シリアル No.		
FW トピ石 傷A フレ 外装 小 ホイル エアロ A・U A・曲 A・フレ	長さ 幅 高さ 最大積載量 484cm 188cm 210cm Kg			
内装 ヨゴレ シシ ヤブレ コゲ コゲ穴 オーディオ穴 スレ				