

2009 Toyota Prius S

OVERALL
3.5

EXTERIOR
-

INTERIOR
-

MODEL CODE
ZVW30

DISPLACEMENT
1,797 cc

YEAR / REG.
2009/10

MILEAGE
42,300 km

DOORS
5

SEATS
5

DRIVETRAIN
2WD (FF)

TRANSMISSION
AT

FUEL
Hybrid (Petrol)

STEERING
Right

EXTERIOR COLOR
Blue

BODY TYPE
Hatchback

CHASSIS NO.
ZVW30-5074271

DIMENSIONS (L X W X H)
446 × 175 × 149 cm

SALES POINTS

Alloy Wheels
Navigation System

Back Camera

INSPECTOR REPORT

JAAA appraisal: Exterior 3.5, Interior 4. A.A.U. indicates multiple items. Exterior has touch-up repair marks and light scratches. Steering wheel has scuffs/scratches. Rear (roof) spoiler paint is faded and peeling (W2108S). Both headlights are cloudy/dull. Driver's seat has medium wrinkles/scuffs. Dashboard, passenger seat, console, right front door trim, rear seat back, and other trims show minor scuffs, scratches, wrinkles, and dirt.

ORIGINAL JAPANESE AUCTION SHEET

H21 / 10月		トヨタ プリウス S		5 コンパクト/ハッチバック		3.5	
車種 自家用・その他 ()		排気量 1800 cc		型式 ZVW30		内装 A・⑤・C	
年式 8年 10月		燃料 ガソリン		ディーゼル		後付選り品 (色替・取付等)	
走行 42,300 km		インパネ		AT			
外装色 ライトブルー		カラーNo.		エアコン		新着品のみ O印 を記入	
()		()		()			
左・前		ディーラー		走行 13,190 km		エレクトロニクス	
セールスポイント		CD/バックカメラ/TC横滑り防止装置 (ESC) /運転席エアバック/盗難防止システム/スマートキー/キーレスエントリー/ABS/助手席エアバック/サイドエアバック/メモリーナビゲーション/セグメントV/衝突安全ボディ/アイドリングストップ					
検査記入欄		A 欠損 B 欠損 C 欠損 D 欠損 E 欠損 F 欠損 G 欠損 H 欠損 I 欠損 J 欠損 K 欠損 L 欠損 M 欠損 N 欠損 O 欠損 P 欠損 Q 欠損 R 欠損 S 欠損 T 欠損 U 欠損 V 欠損 W 欠損 X 欠損 Y 欠損 Z 欠損					
月 日		ZVW30-5074271					
車種		ZVW30-5074271					
車種		ZVW30-5074271					