


2010 BMW_Mini BMW Mini Convertible Cooper S Convertible		OVERALL R	
		EXTERIOR -	INTERIOR -
MODEL CODE ABA-MS16	DISPLACEMENT 1,598 cc		
YEAR / REG. 2010/05	MILEAGE 82,200 km		
DOORS 2	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Red	BODY TYPE Convertible		
CHASSIS NO. WMWMS32040TJ93291	DIMENSIONS (L X W X H) 372 × 169 × 142 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Interior dirt and stains, some scuff cover missing, oil seepage, convertible top faulty, trunk opener switch faulty, aftermarket suspension (unconfirmed), right front instrument panel bracket and side member distorted, uneven repair.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/5月	メーカー MINI MINI	ドア枚数 2	ボディ形状 オープン(カブリオーレ・コンバーチブル)	評価点 R																				
車種 自家用・その他()	排気量 1600 cc	型式 ABA-MS16	内装 A・B・C																					
車検 -年-月/日	燃料 ガソリン	ディーゼル	後日選り品(保証書・取扱説明書等)																					
走行 82,200 km	AT																							
外装色 レッド	カラーNo. 851	エアコン	装備品のみ O印 を記入																					
内装色 ()	車検定済	AW	サンルーフ	革シート																				
左・右・後 左・右・後	16,840円	エレクトロニクス	ナビ	TV																				
キーレス																								
セールスポイント ★社外マフラー ★シートカバー																								
検査記入欄 内装汚れスレカパー一部欠 オイルにじみ 幌不良 ト ランクオープナースイッチ不良 社外足廻り? 右フイ ンパネブラケット・サイドメンバー歪 補修ムラ	<table><tr><td>A</td><td>キズ</td><td>U</td><td>ヘッドライト</td><td>B</td><td>キズ・ヘッド</td><td>P</td><td>色あせ・汚れ</td><td>G</td><td>ガラスキズ</td></tr><tr><td>W</td><td>燃費</td><td>S</td><td>サビ</td><td>C</td><td>腐食</td><td>X</td><td>交換部</td><td>XX</td><td>交換済</td></tr></table> 売却日 月 日 までに名義できる方 車体番号 WMWMS32040TJ93291 シリアル No. 車重 371 cm 168 cm 138 cm Kg				A	キズ	U	ヘッドライト	B	キズ・ヘッド	P	色あせ・汚れ	G	ガラスキズ	W	燃費	S	サビ	C	腐食	X	交換部	XX	交換済
A	キズ	U	ヘッドライト	B	キズ・ヘッド	P	色あせ・汚れ	G	ガラスキズ															
W	燃費	S	サビ	C	腐食	X	交換部	XX	交換済															