


2010 Honda CR-Z Alpha		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZF1	DISPLACEMENT 1,496 cc		
YEAR / REG. 2010/06	MILEAGE 103,662 km		
DOORS 3	SEATS 4		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Coupe		
CHASSIS NO. ZF1-1010501	DIMENSIONS (L X W X H) 408 × 174 × 140 cm		
SALES POINTS			
Alloy Wheels		Cruise Control	
INSPECTOR REPORT			
Front windshield stone chip, left front door A2, left rear door A2, rear bumper A2, right rear door A2, right front door A2, right front fender A2, right rear fender A2, roof A2, hood A2, trunk A2, interior dirt, interior stains, interior burn holes, interior audio holes, interior scuffs			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/6月	メーカー ホンダ	ドア枚数 3	ボディ形状 クーペ	評価点 R
車名 C R - Z	グレード α	駆動方式 4WD	車種区分 軽自動車	
車種 自家用・その他 ()	排気量 1490 cc	型式 DAA-ZF1	登録形式	内装 A・B・C
年 9	月 6	抹消 燃料 ハイブリッド	ディーゼル ()	後日添付品 (保証書・取扱説明書 等)
走行 103,662 km	マイル 66,200	AT		
外装色 ミラノレッド	カラーNo. R81	エアコン AG・AG・WAG・()		装備品のみ O印 を記入
()	内装色 その他	乗車定員 4人	PS	サンルーフ
左・右 左・右	ディーラー 走行	12,590円	ABS	ナビ
セールスポイント	0			
検査記入欄				
	修復歴 無			
	A キズ U ヘビオキズ B キズ・ヘビキズ P 色あせ・剥き G ガラスキズ			
	W 経年劣化 S サビ C 腐食 X 交換部品 XX 交換部品			
	売却月 月 日 までに名義できる方			
	車体番号 ZF1-1010501			
	FW 1500 フレ 外装 小 ホイル エアロ			
	内装 1500 シア ヤブレ 1500 コグス オーディオ			
	車重 1400 kg			