


2010 Honda Fit X		OVERALL	
		4	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-GE8	DISPLACEMENT 1,496 cc		
YEAR / REG. 2010/01	MILEAGE 68,195 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Silver	BODY TYPE Hatchback		
CHASSIS NO. GE8-1302806	DIMENSIONS (L X W X H) 390 × 170 × 153 cm		
SALES POINTS			
Alloy Wheels Back Camera		Cruise Control Navigation System	
INSPECTOR REPORT			
Exterior scratches and dents, front windshield stone chip, interior dirty, scuffs on aero parts.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/1月	メーカー ホンダ	ドア枚数 5	ボディ形状 コンパクトハッチバック	評価値 4
車名 フィット	グレード X	駆動区分 2WD	4WD	
車種 自家用・その他 ()	排気量 1500 CC	型式 DBA-GE8	通称 内装	A・B・C
年 10年	月 3月	抹消 燃料 ハイブリッド ()	後付選り品 (保証書・取扱説明書 等)	
走行 195,681 km	マイル AT	シフト AT		
外装色 ストームシルバー・メタリック	カラーNo. ()	エアコン A・A・G・W・G ()	装備品のみ O印 を記入	
内装色 ()	乗車定員 5人	サンルーフ ()	革シート ()	
左・前 ディーラー・走行	リサイクル料 10,810円	預託料 ()	エブリック ()	その他 ()
セールスポイント 純正ナビ/シートヒーター/ヘッドランプ HID/Bluetooth接続/ETC/BD付ABS/クルーズコントロール/バックモニター/ワンセグTV				
検査記入欄		修復歴 有・無 ()		
外装AU		A キズ U ヘッドライト B キズ・ヘッ P 色あせ・ボケ G ガラスキズ W 補修跡 S サビ C 腐食 X 交換歴 YX 交換歴		
		登録No. 月 日 までにご査度できる方 名度中		
		車体番号 GE8-1302806		
FW ()	トビ ()	ワレ ()	外装 ()	小 ()
内装 ()	シロ ()	ヤブレ ()	コガ ()	コガ穴 ()
			オーディーオ ()	エアロ ()
			シリアル No. ()	車種 ()
			長さ ()	高さ ()
			最大積重量 ()	kg