

2010 Honda INSIGHT G		OVERALL	
		R	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DAA-ZE2	DISPLACEMENT 1,339 cc		
YEAR / REG. 2010/04	MILEAGE 78,084 km		
DOORS 5	SEATS 5		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Hybrid (Petrol)	STEERING Right		
EXTERIOR COLOR Other	BODY TYPE Other		
CHASSIS NO. ZE2-1207292	DIMENSIONS (L X W X H) 439 × 169 × 142 cm		
SALES POINTS			
Alloy Wheels			
INSPECTOR REPORT			
Front windshield stone chip. Interior has scratches, stains, burns, holes, scuffs, and tears. Steering wheel has heavy wear, seats are sagging and torn. End panel XX (repaired/replaced), rear side member has a B-grade repair mark. Trunk floor has a B-grade repair mark. Lower support is pushed up.			

ORIGINAL JAPANESE AUCTION SHEET

出品票		形式番号	16223	納税区分	0001	シリアル番号		評価点	
年	月	日	車種	グレード	駆動	評価点			
H 22	4		インサイト	D	G	R			
型式	DAA-ZE2		総重量	1,300	cc	燃料	ガソリン	軽油	
車検	年	月	車種	自家用	シフト	CVT	冷却	AC	純正後備品
走行距離	7	8	0	8	4	km	マイル	0	純正ナビ
外装色	シルバー		色替無	カラーNo.	MF700N	内装色			純正ナビ
車台No.	ZE2-1207292		車検	月	日				純正ナビ
登録No.	抹消		リサイクル	11,460	円	円	円	円	純正ナビ
定員	5	人	積載量	439	kg	cm	169	cm	純正ナビ
輸入車のみ	モダ	年式	輸入区分	ディーラー	並行	ハンドル	左		純正ナビ
セー	ル	ポイント							純正ナビ
・キーレス・ECONモードスイッチ・チルトステアリング・シートリフター・電動格納ミラー・レベライザー									
注意事項・不具合箇所									
検査員記入欄：修復歴「有」の場合は修復箇所・交換箇所を記入									
フロントウィンドー 飛び石									
内装キズ、汚れ、焦げ、穴、スレ、キレ									
ハンドルスレ、シートへたり、切れ									
エンドパネルXX、リヤサイドメンバーB跡									
トランクフロアB跡									
ロアサポート 奥上げ									
ドアミラー	キズ	ヒビ	ワレ						
工具	無	ジャッキ	無						