

2010 Honda Odyssey 2.4 M Aero Package		OVERALL	
		4.5	
		EXTERIOR	INTERIOR
		-	-
MODEL CODE DBA-RB3	DISPLACEMENT 2,354 cc		
YEAR / REG. 2010/01	MILEAGE 99,990 km		
DOORS 5	SEATS 7		
DRIVETRAIN 2WD (FF)	TRANSMISSION AT		
FUEL Petrol	STEERING Right		
EXTERIOR COLOR Pearl White	BODY TYPE Minivan		
CHASSIS NO. RB3-1107721	DIMENSIONS (L X W X H) 480 × 180 × 155 cm		
SALES POINTS			
Alloy Wheels Navigation System		Back Camera	
INSPECTOR REPORT			
Right power folding mirror faulty, small scratches on door mirrors, steering wheel scuff, some light stains in cabin, driver's seat edge scuff, small scratches, small dents, wheel scratches, Bluetooth faulty.			

ORIGINAL JAPANESE AUCTION SHEET

初年度登録 H22/1月	メーカー ホンダ	ドア数 5	ボディ形状 ミニバンワンボックス	評価点 4.5
車名 オデッセイ	グレード 2.4 Mエアロパッケージ	駆動方式 2WD	変速機 4WD	
車種 自家用・その他 ()	排気量 2400 cc	型式 DBA-RB3	通称 A・B・C	
年 99	月 9	日 0	走行 99,990 km	インパネ CVT
所属色 プレミアムホワイトパール	カラーNo. QD・AAG・WAG・()	エアコン QD・AAG・WAG・()	装備品のみ O印 を記入	
内装色 ()	車体定員 7人	サンルーフ	革シート	
ボディ 左・()	輸入 ディーラー・()	走行 13,850円	販売 エフ・エフ・エフ	中古車
セールスポイント				
キーレスエントリー/A B S /運転席エアバック/助手席エアバック/HDDナビ/フルセグTV/ETC/フルエアロ/盗難防止システム/HID・キセノン・ディスチャージ/横滑り防止装置(E S C) /3列シート/フルフラット/DVD再生/ミュージックサーバー/CD/Dバックカメラ				
検査記入欄				
右電動格納ミラー不良 ドアミラー小キズ ハンドルスレ ルーム内一部うす汚れ Dシートフチスレ 小キズ 小凹み ホイールキズ Bluetooth不良				
車体番号 RB3-1107721				
車種 ミニバン				
最大積載量 Kg				